0008

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Jch pge

inspection report

Permit No. ACT/015/002

Inspection Date 8/20/92

Permittee/Operator Name WESTERN STATES MINERALS

Business Address 84 GLEN CARRAN CIRCLE

City SPARKS State NEVADA Zip 89431

Mine J. B. KING (RECLAIMED) ☐ Surface ☒ Underground ☐ Other

County EMERY State UT

Company Official(s) NONE

State Official(s) TOM MUNSON AND SUSAN WHITE

Time of inspection 12:00 ☐ a.m. ☒ p.m. to 2:30 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection JUNE 26, 1992 Weather conditions SUNNY

Acreage 480 ☐ Permitted ~~30~~ ☐ Disturbed 30 ☐ Regraded 30 ☐ Seeded 30 ☐ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☒	☐	☐	☒
— Diversions	☐	☐	☐	☐
b Sediment ponds and impoundments	☒	☐	☐	☒
c Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☒	☐	☐	☐
— Effluent limitations	☒	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☐	☐	☒	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☐	☐	☒	☐
11. Contemporaneous reclamation	☒	☐	☐	☐
12. Backfilling and grading	☒	☐	■	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☒	☐	☐	☐
15. Cessation of operations	☒	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	■	☒
17. Other transportation facilities	■	☐	☒	☐
18. Support facilities and utility installations	☐	☐	☒	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/002

Inspection Date 8/20/92

Please number comments to correspond with topics on previous page.

1. Permits: Correspondence from Dianne Nielson to Mr. Crossland on August 19, 1992 extended NOV's # N91-32-6-1, N91-35-6-7 and N91-35-7-1 for submission of abatement plans until September 15 and October 15, 1992 for final abatement.

4a. Work has been preformed on the upperwatershed of the main channel to prevent circumvention of the channel prior to resolution of NOV 91-32-6-1. A significant berm was constructed and the area of disturbance was restricted to the previous channel area. This work was requested by Mr. Henry Sauer in his May 4, 1992 inspection.

6. Sediment Pond and impoundments - The sediment pond had water in it and a fair amount of sediment. The amount of sediment could not be

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/002

Inspection Date 8/20/92

Please number comments to correspond with topics on previous page.

ascertained based on ocular estimates and therefore the division requests that the operator submit some verification of capacity to meet the permitted storm volumes and clean out the sediments if required. No mention of any problems was noted in the 5/2/92 Pond inspection report.

4C. Other sediment control measures - Pending the outcome of the abatement plan for NOV N91-35-6-2 the use of silt fences and straw mulch to control erosion on site will not be assessed. Certain silt fences were not in adequate repair and some erosion was occurring. A large amount of weeds have surfaced on the site obscuring erosion which was evident in past inspections.

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/002

Inspection Date 8/20/92

Please number comments to correspond with topics on previous page.

13. Revegetation - The site has experienced a good water year and growth of vegetation has responded accordingly. Unfortunately the amount of Halogeton a noxious weed, has responded as well. Shrubs in the drainages or in the proximity are very robust and doing well. Reseeding may be an option in the areas where Halogeton has taken over.

16. Roads - Maintenance of the road to the subsidence areas may be necessary if passage becomes more severe due to recent storm events.

Copy of report mailed to WSM Dwight Crossland; OSM/Brian Smith

Copy of report given to Joe Helfrich

Inspector's signature Tom Munson No. 25

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer