0006

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/015/004

Inspection Date 10/28/87

Permittee/Operator Name Beaver Creek Coal Co.

Business Address P.O. Box 1378

City Price State Utah Zip 84501

Mine Huntington Canyon #4 ☐ Surface ☒ Underground ☐ Other

County Emery State Ut.

Company Official(s) Dan Guy

State Official(s) Bill Malencik,

Time of inspection 10:00 ☒ a.m. ☐ p.m. to 1: ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection Sept 1987 Weather conditions Clear/Cool/Site Dry

Acreage 2600 ☐ Permitted 12.5 ☐ Disturbed 12 ☐ Regraded 12 ☐ Seeded 12.5 ☐ Bonded

Enforcement Action None

Maintenance Items: Noted On Page 2.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☐
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☒	☐	☐	☐
— Effluent limitations	☐	☒	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☐	☐	☒	☐
9. Protection of fish, wildlife, and related environmental values	☐	☒	☐	☐
10. Slides and other damage	☐	☐	☒	☐
11. Contemporaneous reclamation	☐	☐	☒	☐
12. Backfilling and grading	☐	☐	☒	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☐	☐	☒	☐
15. Cessation of operations	☐	☐	☒	☐
16. Roads				
— Construction	☒	☐	☐	☐
— Drainage controls	☒	☐	☐	☐
— Surfacing	☒	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☐	☐	☒	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/004

Inspection Date 10/28/87

Please number comments to correspond with topics on previous page.

General Comment. The reclaimed site continues to look good with no significant problems detected since last visit in the latter part of August where no big game use was detected, now deer signs were observed including moderate to heavy use of the planted browse species, primarily Mtn. Mahogany.

Signs & Markers. Some of the perimeter markers are difficult to see and need a new coat of paint. This maintenance work should be completed, as a suggestion before adverse weather sets in.

Other Sediment Control Measures. Some small erosion was detected on the lower pad. This was primarily rill type erosion about 5 inches deep. Some erosion protection should be undertaken before such rills erode further and fail to meet performance standards.

Copy of report mailed to Dan Guy, BCCC, 10/30/87; (Brain Smith, OSM. Joe Helfrich DOGM) sent To SLC

Copy of report ~~given~~ to PEO.

Inspector's signature Tom J. Malencik 10/30/87 No. 26.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE