0009

9-10-87

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/015/004

Inspection Date 8/24/87

Permittee/Operator Name Beaver Creek Coal Co.

Business Address P.O. Box 1378

City Price, Utah State _____ Zip 84501

Mine Huntington Canyon #4 ☐ Surface ☐ Underground ☒ Other

County Emery State Utah.

Company Official(s) None Available On Field Portion – Dan Guy, Records.

State Official(s) Wm. J Malencik, Harold Sandbeck

Time of inspection 11:00 ☒ a.m. ☐ p.m. to 2:30 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection 7/22/87 Weather conditions Clear/Warm

Acreage 2600 ☐ Permitted 125 ☐ Disturbed 12 ☐ Regraded 12 ☐ Seeded 125 ☐ Bonded

Enforcement Action None.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
– Stream channel diversions	☒	☐	☐	☐
– Diversions	☒	☐	☐	☐
– Sediment ponds and impoundments	☒	☐	☐	☒
– Other sediment control measures	☒	☐	☐	☐
– Surface and groundwater monitoring	☒	☐	☐	☒
– Effluent limitations	☒	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☐	☐	☒	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☒	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☒	☐
12. Backfilling and grading	☐	☐	☒	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☒	☐	☐	☐
15. Cessation of operations	☐	☐	☒	☐
16. Roads				
– Construction	☐	☐	☒	☐
– Drainage controls	☐	☐	☒	☐
– Surfacing	☐	☐	☒	☐
– Maintenance	☐	☐	☒	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☐	☐	☒	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/004

Inspection Date 8/27/87

Please number comments to correspond with topics on previous page.

SIGNS & MARKERS Appropriate signs & markers are in place.

Topsoil. The small topsoil pile contains an excellent cover of grass and some woody plants. The topsoil will be utilized to rehab the sediment pond at a later date when the sediment pond has outlived it usefulness.

Sediment Pond. Sediment pond contained water and was about two feet below discharge level.

Surface & Groundwater Monitoring: The records were reviewed and found to be in order on the five water monitoring stations.

Revegetation. The grass is still green, headed out, and some seeds are starting to fall on the soil surface. No significant evidence of any wildlife or domestic livestock use on either the lower or upper pad.

Two small areas on the upper pad contain a dense vigorous growth of Canadian thistle. The larger area is about 50'x50', the smaller about 25'x10'.

Grass has emerged from the diversions on the ripped haul road. This work was performed by USFS employees covered in a previous report.

Copy of report mailed to DAN GUY, BCCC; Donna Griffin, OSM

Copy of report given to Joe Helfrich, DOGM.

Inspector's signature [signature] 9/2/87 No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE