* 0011

Document Information Form

Mine Number: C/015/004

File Name: Internal

To: DOGM

From:

Person N/A

Company BEAVER CREEK COAL COMPANY

Date Sent: MAY 28, 1987

Explanation:

COPY OF LETTER

cc:

File in:
C/ 015 , 004 , Internal
Refer to:
- ☐ **Confidential**
- ☐ **Shelf**
- ☐ **Expandable**

Date _____ For additional information

Beaver Creek Coal Co.
O. Box 1378, Price, UT 84[illegible]01
pector H. P. Austin
ers Bill Malencik - DOGM
Dan Guy, BCCC

Date: 5-28-87
Inspection Type complete, joint

Accompanied the above on a complete, routine inspection. This site was reclaimed during fall of 1985, refer to OSM/MEIR dated 6-12-86 for report on bond release inspection and permit stipulations status [All stipulations have been resolved.] We walked the entire upper and lower reclaimed areas, and checked revegetation success, erosional development and runoff control.

There are no erosional problems evident on the reclaimed areas - the silt fencing (temporary) was removed from the upper bench except for one small area. A few small rills were developing in these areas - which can be repaired by hand.

The extra wet spring has helped vegetation reestablishment - most areas show good success in terms of cover and diversity - there are a few spots which will need reseeding - particularly the gravelly pad on far east end of former portals pad. Some of the shrubs show signs of elk browse - particularly the bitter brush (almost gone) and heavy browse on the mountain mahogany - however - they have survived.

Sediment pond inspections were current thru 5/87; this two-cell pond does not discharge according to NPDES reports and operators. Required water sampling is cu[illegible] indicated the road use permit has been t[illegible] regraded/seeded the road bed as per USFS

Performance standards indicated as not applicable,

File in:
- ☐ Confidential
- ☐ Shelf
- ☐ Expandable

Refer to Record No 0011 Date
In C/ 015, 004, Internal
For additional information

Beaver Creek Coal Co.

P.O. Box 1378, Price, UT 84501

Date: 5-28-87

Inspector H. P. Austin

Inspection Type complete, joint

Others Bill Malencik - DOGM
Dan Guy, BCCC

Accompanied the above on a complete, routine inspection. This site was reclaimed during fall of 1985, refer to OSM/MEIR dated 6-12-86 for report on bond release inspection and permit stipulations status [All stipulations have been resolved.] We walked the entire upper and lower reclaimed areas, and checked revegetation success, erosional development and runoff control.

There are no erosional problems evident on the reclaimed areas - the silt fencing (temporary) was removed from the upper bench except for one small area. A few small rills were developing in these areas - which can be repaired by hand.

The extra wet spring has helped vegetation reestablishment - most areas show good success in terms of cover and diversity - there are a few spots which will need reseeding - particularly the gravelly pad on far east end of former portals pad. Some of the shrubs show signs of elk browse - particularly the bitter brush (almost gone) and heavy browse on the mountain mahogany - however - they have survived.

Sediment pond inspections were current thru 5/87; this two-cell pond does not discharge according to NPDES reports and operators. Required water sampling is current. U.S.F.S. correspondence indicated the road use permit has been terminated as BCCC has regraded/seeded the road bed as per USFS guidelines.

Performance standards indicated as not applicable, do not exist on site.

-HPA-