7095 0002

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

RECEIVED DEC 28 1989 DIVISION OF OIL, GAS & MINING

inspection report

Permit No. INA/015/004

Inspection Date Dec 19, 1989

Permittee/Operator Name Beaver Creek Coal Co.

Business Address P.O. Box 1378

City Price State Ut Zip 84501

Mine Huntington #4 ☐ Surface ☒ Underground ☐ Other

County Emery State Ut.

Company Official(s) Dan Guy

State Official(s) Bill Malencik

Time of Inspection 8:00 ☐ a.m. ☐ p.m. to 11:00 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection 11/9/89 Weather conditions Clear/Cool

Acreage 2600 ☐ Permitted 125 ☐ Disturbed 12 ☐ Regraded 12 ☐ Seeded 125 ☐ Bonded

Enforcement Action

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☒	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/004

Inspection Date 12/10/89

Please number comments to correspond with topics on previous page.

General Comments. The road to the mine site on the upper end was snow covered with 6"-8" on the upper road turnaround. The reclaimed mine area being a southerly exposure was void of snow.

Signs & Markers. New ID signs have been installed together with water monitoring station signs.

Diversions. Several diversions were checked on no problems noted.

Sediment Pond. Sediment pond contained water, was stable, and no evidence of seasonal discharge

Other Sediment Control. Silt fence on the lower pad is fully functional and looks like it has recently been maintained with new fabric

Road. Operator stated that the Forest Service had recently removed part of the guard rails on the lower bridge that crosses Hunting Creek

Copy of report mailed to SLC For DOGM/Joe Helfrich; OSM/Brian Smith

Copy of report given to BCCC/Dan Guy.

Inspector's signature Tim J Malenick No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

12/21/89

DOGM/IR-2

an equal opportunity employer

11/86 001049