0004

RVS

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/015/004

Inspection Date OCTOBER 4, 1989

Permittee/Operator Name BEAVER CREEK COAL COMPANY

Business Address P.O. BOX 1378

City PRICE State UTAH Zip 84501

Mine HUNTINGTON #4 ☐ Surface ☒ Underground ☐ Other

County EMERY State UTAH

Company Official(s) KEN FLECK

State Official(s) TOM MUNSON, RICH SMITH

Time of inspection 1:00 ☐ a.m. ☒ p.m. to 2:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 9/14+15 Weather conditions SUNNY

Acreage 2600 ☒ Permitted 12.5 ☒ Disturbed 12 ☒ Regraded 12 ☒ Seeded 12.5 ☒ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a) — Stream channel diversions	☐	☐	☐	☐
b) — Diversions	☐	☐	☐	☐
c) — Sediment ponds and impoundments	☐	☐	☐	☐
d) — Other sediment control measures	☒	☐	☐	☒
e) — Surface and groundwater monitoring	☐	☐	☐	☐
f) — Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☒	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/004

Inspection Date 10/4/89

Please number comments to correspond with topics on previous page.

(4d) The silt fences adjacent to the topsoil pile where nonfunctional because of undercutting and repairs were made at the time of inspection to correct the problem by B.C.C.C. representative Kim Fleck. All other controls were functioning as intended.

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE