0006

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/015/007

Inspection Date August 14, 1987

Permittee/Operator Name California Portland Cement

Business Address 695 South Rancho Avenue

City Colton State CA Zip 92324-0514

Mine Hidden Valley ☐ Surface ☒ Underground ☐ Other

County Emery State UT

Company Official(s) None

State Official(s) Harold G. Sandbeck and Bill Malencik

Time of inspection 10:00 ☒ a.m. ☐ p.m. to 1:00 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection July 7, 1987 Weather conditions Clear/Warm

Acreage 960 ☒ Permitted 7 ☒ Disturbed 7 ☒ Regraded 7 ☒ Seeded 7 ☒ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☒	☐	☐	☐
b Diversions	☒	☐	☐	☐
c Sediment ponds and impoundments	☐	☐	☒	☐
d Other sediment control measures	☒	☐	☐	☒
e Surface and groundwater monitoring	☒	☐	☐	☐
f Effluent limitations	☐	☐	☒	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☐	☐	☒	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☐	☐	☒	☐
11. Contemporaneous reclamation	☒	☐	☐	☐
12. Backfilling and grading	☒	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☐	☐	☒	☐
15. Cessation of operations	☐	☐	☒	☐
16. Roads				
a Construction	☒	☐	☐	☐
b Drainage controls	☒	☐	☐	☒
c Surfacing	☒	☐	☐	☐
d Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☐	☐	☒	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/007

Inspection Date August 14, 1987

Please number comments to correspond with topics on previous page.

General Comments: The mine site area appears stable and looks good. The ground was wet indicating recent runoff. No significant erosion was observed on the mine site.

2.) Signs and Markers: The main sign at the end of the black top road has been installed. The sign has been updated and is current.

4.d.) The silt fences along the slope and around the riprap channel appear functional.

16.d.) The main entrance haul road berms are doing a good job of preventing erosion. Evidence of water puddling was noticed behind road berms. The road vegetation is predominantly weeds and appears well established.

Copy of report mailed to Donna Griffin, OSM; John Rains, CPC

Copy of report given to Joe Helfrich, DOGM

Inspector's signature Harold D. Sandvik 14 August 1987 No. 27

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer