11-1389 7145 0007

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No ACT/015/009

Inspection Date Nov. 9, 1989

Permittee/Operator Name BEAVER CREEK COAL COMPANY

Business Address P.O. BOX 1378

City PRICE State UT Zip 84501

Mine TRAIL MOUNTAIN #9 ☐ Surface ☒ Underground ☐ Other

County EMERY State UT

Company Official(s) NONE

State Official(s) BILL WAKMACK

Time of inspection 11:00 ☒ a.m. ☐ p.m. to 12:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection Oct. 4, 1989 Weather conditions CLEAR & BREEZY

Acreage 415 ☒ Permitted 8.8 ☒ Disturbed ☐ Regraded ☐ Seeded 8.8 ☒ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☒	☐	☐	☐
b Diversions	☐	☐	☐	☐
c Sediment ponds and impoundments	☒	☐	☐	☐
d Other sediment control measures	☒	☐	☐	☒
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a Construction	☐	☐	☐	☐
b Drainage controls	☐	☐	☐	☐
c Surfacing	☐	☐	☐	☐
d Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date NOV. 9, 1989

Please number comments to correspond with topics on previous page.

4d. SILT FENCES & STRAW BALES WERE IN GOOD CONDITION. OLD STRAW BALE REMAINS ALONG THE SLOPE ADJACENT TO THE COAL STOCKPILE HAVE BEEN REMOVED.

16d. ROAD SURFACES NEAR the coal stockpile & lower gate were dry & a light dust accumulation was starting to become noticeable. Mr. Gary Curtis was made aware of the potential problem & said he would water the road surface to reduce/eliminate dust. Also, Mr. Curtis stated that BCCC might try a dust suppressant along this area to alleviate some of the dust problems.

Copy of report mailed to SLC: Lee Hafeich (DOGM), Brian Smith (OSM)

Copy of report given to BCCC for Dan Guy, PFO

Inspector's signature William A. Warnock 11/9/89 No. 30

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE