0005

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/009

Inspection Date 11/14/90

Permittee/Operator Name Beaver Creek Coal Company (BCCC)

Business Address P.O. Box 1378

City PRICE State UTAH Zip 84501

Mine TRAIL MTN. #9 ☐ Surface ☑ Underground ☐ Other

County EMERY State UTAH

Company Official(s) DAN GOY

State Official(s) HENRY SAUER

Time of inspection 2:30 ☐ a.m. ☒ p.m. to 5:00 ☐ a.m. ☒ p.m. ☑ Partial ☐ Complete

Date of last inspection September 7, 1990 Weather conditions Clear and cool

Acreage 141.5 ☒ Permitted 8.8 ☑ Disturbed ☐ Regraded ☐ Seeded 8.8 ☒ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☒

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 11/14/90

Please number comments to correspond with topics on previous page.

Dan Guy accompanied the undersigned inspector on this partial state inspection. Weather conditions were clear and cool. No evidence of recent rain existed.

3) Topsoil: Substitute topsoil originally excavated from the operations pad landfill and subsequently placed adjacent to the mine office, was tested (field site revegetation trial) to determine its suitability as a plant growth medium. The field trials appeared to be successful thus to afford operational space the test plots have been removed and topsoil material which was exploited by roots was excavated and placed in a new portion of the existing topsoil stockpile. The permittee was informed that once all of the amendments are finalized, the surface facilities map must be revised to depict all changes related to the amendments.

In addition Dan Guy and myself surveyed the riparian area which will be disturbed by the culvert extension. A rough estimate of the areas where topsoil could be salvaged was discussed. I requested that I be in attendance when topsoil salvage operations occured.

Copy of report mailed to Dan Guy (BCCC) ; John Kathman (OSM)

Copy of report given to JOE HELFRICH (DOGM)

Inspector's signature Henry Sauer No. 32

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 11/14/90

Please number comments to correspond with topics on previous page.

4) ~~Backfilling~~ Hydrologic Balance - Sediment Ponds and Impoundments: The sediment was in the process of being cleaned out. I informed Dan to take a sample of the sediment pond waste to determine the acid and/or toxic forming potential of the sediment.

13) Support facilities and utility installations: The valve on the rock dust bins is not operating properly. Rock dust is spewing out. Dan Guy stated that he would fix the valve.

Copy of report mailed to Dan Guy (BCCC); John Kathman (OSM)

Copy of report given to Joe Helfrich (DOGM)

Inspector's signature [signature] No. 32

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE