0037

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Job page

inspection report

Permit No. ACT/015/009
Inspection Date May 3, 1990

Permittee/Operator Name Beaver Creek Coal Co.
Business Address P.O. Box 1378
City Price State Ut Zip 84501
Mine Trail Mtn #9 ☐ Surface ☒ Underground ☐ Other
County Emery State Ut
Company Official(s) Dan Gary
State Official(s) Bill Malencik
Time of inspection 8:00 ☒ a.m. ☐ p.m. to 11:00 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete
Date of last inspection 4/10/90 Weather conditions Cool / Pt. Cloudy / Dry Mine Site
Acreage 1415 ☐ Permitted 8 ☐ Disturbed ☐ Regraded ☐ Seeded 8 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☒

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date May 3, 1990

Please number comments to correspond with topics on previous page.

General Comments: Dan Guy the operators representative and the undersigned walked over the surface mine area and checked on the condition and functionability of most environmental control measures.

Evidence of recent surface environmental work by the operator included the installation of a silt fence on the topsoil pile, activating the coal storage/loading area sprinkling system, and a general cleanup of the site. Also, the operator stated that they had recently noted the sediment pond decreases attachment had become loose and they reattached it. He mentioned it is fully functional; however, a more substantial arrangement will be done when the pond is decanted.

Topsoil: The topsoil pile near the portal has a good grass cover, is adequately protected, and no problems were noted.

Diversion: The lower diversion that drains into the sediment pond had recently been cleaned. Culverts, concrete ditch, and other water conveyance systems

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009.

Inspection Date 5/3/90

Please number comments to correspond with topics on previous page.

were checked and were in compliance.

Revegetation. The operator last week hydroseeded/mulched the sediment pond embankment.

He, Dan Guy, stated that on the last inspection the inspector suggested that the outslope from the road above the sediment pond be seeded. The operator stated this would be done this fall together with the outslope on the upper exemption area.

Support Facilities. The operator stated they had removed an underground, unused, and sound fuel tank that was located adjacent to the office

Copy of report mailed to { BCCC/Dan Guy
SLC: OSM/Brian Smith, DOGM/Joe Helfrich

Copy of report ~~given to~~ filed RFO

Inspector's signature Tim J. Malencik No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE