7145 0045

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gh gyl

inspection report

Permit No. ACT/015/009
Inspection Date Jan 11, 1990

Permittee/Operator Name Beaver Creek Coal Co.
Business Address P.O. Box 1378
City Price State Ut Zip 84501
Mine Trail Mtn #9 ☐ Surface ☒ Underground ☐ Other
County Emery State Ut
Company Official(s) Dan Guy
State Official(s) Bill Malencik & Harold Sandbeck
Time of inspection 8:00 ☒ a.m. ☐ p.m. to 10:30 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete
Date of last inspection 12/19/89 Weather conditions Pt. Cloudy
Acreage 1415 ☐ Permitted 88 ☐ Disturbed ☐ Regraded ☐ Seeded 88 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☒	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 1/11/90

Please number comments to correspond with topics on previous page.

Permit. Permit expires on February 19, 1990. The ICR has been completed and the T.A is scheduled to be completed about Feb 1.

Topsoil. The topsoil pile was checked. A new silt fence has been installed around the topsoil pile.

Stream Diversions. The two stream channel diversions were checked. The main drainage was iced over and water was running under the ice. The side drainage was dry. Both culverts were open and clean.

Sediment Pond. Sediment pond contained water. From the general appearance ie., ice buildup, the main source of water appears to be coming from the mine water discharge pipe.

Diversion. One six inch plastic downspout above the tipple was blocked and the operator had the pipe flushed and cleaned by the end of this inspection.

Roads. The coal fines carried by the trucks to the Emery County Road was checked. Most of these fines will drain into the road ditch, thence to the catchment through a culvert and into the sediment pond. Since the area has experienced a lack of moisture, the operator was requested to sweep the coal fines into the ditch.

Copy of report mailed to SLC For: OSM/Brain Smith; DOGM/Joe Helfrich

Copy of report given to BCCC/Dan Guy

" " " filed PFO

Inspector's signature [signature] No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

1/16/90

DOGM/IR-2

an equal opportunity employer

11/86 001049