0010

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/009

Inspection Date 6/21/91

Permittee/Operator Name BEAVER CREEK COAL CO.

Business Address P.O. BOX 1378

City PRICE State UT Zip 84501

Mine TRAIL MTN #9 ☐ Surface ☒ Underground ☐ Other

County EMERY State UT

Company Official(s) DAN GW

State Official(s) TOM MUNSON HUGH KLEIN

Time of inspection 11:00 ☒ a.m. ☐ p.m. to 1:00 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection 5/23/91 Weather conditions SUNNY

Acreage 1415 ☒ Permitted 8.8 ☒ Disturbed ☐ Regraded ☐ Seeded 8.8 ☒ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
b Diversions	☒	☐	☐	☒
a Sediment ponds and impoundments	☒	☐	☐	☒
d — Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 6/21/91

Please number comments to correspond with topics on previous page.

The entire site was walked and no problems were noted. The site is being upgraded and such things as a new bathhouse has been constructed, parking lots upgraded and enlarged, stacking tubes for coal loadout added etc. Overall the site is very well organized and efficiently run.

3. Topsoil - It was inspected and the branches and woody material found in it was thought to be of no significance and would possibly provide detritus to the pile.

4 b. Diversions - Are all clean and trash sacks were clean, as well.

c. Sediment pond was dry and clean

d. All alternative control areas were well maintained.

Copy of report mailed to BCCC/DAN GUY; OSM/BRIAN SMITH

Copy of report given to JOE HELFRICH DOGM

Inspector's signature Tom Munson No. 25

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE