0011

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Gd page

inspection report

Permit No. ACT/015/009

Inspection Date 5/23/91

Permittee/Operator Name Beaver Creek Coal Co.

Business Address P.O. Box 1378

City Price State Ut Zip 84501

Mine Trail Mtn #9 ☐ Surface ☒ Underground ☐ Other

County Emery State Ut

Company Official(s) Mel Conrad

State Official(s) Bill Malencik & Hugh Klein

Time of inspection 8:00 ☒ a.m. ☐ p.m. to 1:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 4/30/91 Weather conditions Cloudy / lt Rain

Acreage 1415 ☐ Permitted 88 ☐ Disturbed ☐ Regraded ☐ Seeded 88 ☐ Bonded

Enforcement Action None ?
✓ Maint items

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☒
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☐
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐

	YES	NO	N/A	COMMENTS
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 5/23/91

Please number comments to correspond with topics on previous page.

Permit. The new federal lease has been approved. The mine plan states that no additional surface disturbance will occur as a result of the new lease.

Topsoil. Some woody material up to 1/2 inch in diameter was noted in the topsoil pile. This small amount was only on the lower portion of the pile. Operator should remove the woody material.

Stream Channel Diversion. The trash rack on the diversion above the topsoil pile is in need of routine maintenance.

Diversion. The culvert on the cement lined ditch between the bathhouse and shop needs to be cleaned.

Other Sediment Control. The operators representatives stated they had ordered and received new silt fence material that will be installed around the topsoil pile next tuesday 5/28 (replacing existing silt fence).

Other. The current mine map shows that the disturbed area has been extended on an old exploratory PRE-SMCRA road beyond the powder magazines. This will be discussed with the permittee when he returns from vacation.

Copy of report mailed to BLM/Dan Guy, OSM/Brian Smith, DOGM/Joe Helfrich

Copy of report ~~given to~~ filed PFO

Inspector's signature Wm. J. Malencik No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

5/24/91