0014

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

UT7145

inspection report

Permit No. ACT/015/009

Inspection Date 4/3/91

Permittee/Operator Name Beaver Creek Coal Co.

Business Address P.O. Box 1378

City Price State Utt Zip 84501

Mine Trail Mtn #9 ☐ Surface ☒ Underground ☐ Other

County Emery State

Company Official(s) None

State Official(s) Bill Malencik

Time of inspection 11:00 ☐ a.m. ☐ p.m. to 2:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 3/25/91 Weather conditions Windy/cloudy/cool

Acreage 1415 ☐ Permitted 88 ☐ Disturbed ☐ Regraded ☐ Seeded 88 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☒
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☒

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 4/3/91

Please number comments to correspond with topics on previous page.

General Comments This partial inspection was conducted without permittee participation from the Price office. Checked in the mine office

Topsoil. Additional soil had been added to the topsoil pile adjacent to the main portal

Sediment Pond. The sediment pond contained runoff and was low. Pond embankment, inlet and outlet were stable.

Non Coal Waste. Non-coal waste is stored in dump-containers immediately above the sediment pond. The area was in reasonable good shape when considering the ongoing construction.

Support facilities. The bathhouse is under construction. A new entry way is being added to the existing facility.

Copy of report mailed to BCCC/Dan Guy; OSM/Brian Smith; DOGM/Joe Helfrich

Copy of report ~~given~~ filed to RFO

Inspector's signature [signature] No. Z6

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

5/9/91

DOGM/IR-2

an equal opportunity employer

11/86 001049