0017

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gd pgl

inspection report

Permit No. ACT/015/009
Inspection Date 3/25/91

Permittee/Operator Name Beaver Creek Coal Co.
Business Address P.O. Box 1378
City Price State Ut Zip 84501
Mine Trail Mtn #9 ☐ Surface ☒ Underground ☐ Other
County Emery State Ut
Company Official(s) Dan Guy
State Official(s) Bill Malencik
Time of inspection 9:00 ☒ a.m. ☐ p.m. to 2:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 2/28/91 Weather conditions Clear/Cool
Acreage 1415 ☐ Permitted 88 ☐ Disturbed ☐ Regraded ☐ Seeded 88 ☐ Bonded
Enforcement Action

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☒
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☒

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 3/25/91

Please number comments to correspond with topics on previous page.

General Comments: The surface facilities are currently undergoing reconstruction ie; both houses, tipple, and substation.

Topsoil: The topsoil pile was checked and no problems noted.

Stream Channel Diversion: The culvert extension has been completed on Cottonwood Creek. The trash rack is in place.

Sediment Pond: The sediment pond had recently been cleaned. It was suggested the permittee do some additional work on the inlet protection.

Support Facilities: The coal silo is nearly completed. However, the coal shute is still be utilized until such time that a concrete retaining wall is constructed. This will provide the necessary stability to crusher and beltline.

Conclusion: While the site is under reconstruction, it is the necessary environmental control measures are in place and fully functional.

Copy of report mailed to BCC/Dan Guy; OSM/Brian Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed PFO

Inspector's signature [signature] No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

4/1/91

DOGM/IR-2

an equal opportunity employer

11/86 001049