7145 0012

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gh pgl

inspection report

Permit No. ACT/015/009

Inspection Date 4/7/92

Permittee/Operator Name Mountain Coal Co.

Business Address P.O. Box 1378

City Price State Utah Zip 84501

Mine Trail Mtn #9 ☐ Surface ☒ Underground ☐ Other

County Emery State Utah

Company Official(s) ~~[illegible]~~ DAN GUY

State Official(s) Tom Munson

Time of inspection 1:30 ☐ a.m. ☑ p.m. to 5:00 ☐ a.m. ☑ p.m. ☑ Partial ☐ Complete

Date of last inspection 3/4/92 Weather conditions SUNNY

Acreage 1415 ☐ Permitted 945 ☐ Disturbed ☐ Regraded ☐ Seeded 945 ☐ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☑	☐	☐	☐
— Diversions	☑	☐	☐	☐
— Sediment ponds and impoundments	☑	☐	☐	☑
— Other sediment control measures	☑	☐	☐	☑
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☑	☐	☐	☑
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 4/7/92

Please number comments to correspond with topics on previous page.

4c. The sediment pond had a minor amount of water in it from a discharge from what is called the South Sump. The water level was well below the level of the primary spillway. Some repair work was completed on the inlet to the pond below the concrete inlet. This area of the inlet is below the level of the sediment pond and does not consitute any major inlet control measures. As a maintenance item, it should be inspected periodically by the operator.

4d. The silt fence around the topsoil pile is functionalle and in good repair.

8. The site appeared well maintained and in good repair and all non-coal waste was collected and properly disposed of. All sediment control were maintained.

Copy of report mailed to MCC/DAN GUY; OSM/BRIAN SMITH & ~~[illegible]~~

Copy of report given to DOGM; JOE HELFRICH

Inspector's signature Tom Munson No. 25

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE