STATE OF UTAH
NATURAL RESOURCES
Division of Oil, Gas & Mining

3 Triad Center · Suite 350 · Salt Lake City, UT 84180-1203 · (801) 538-5340



# inspection report

☑ Partial
☐ Complete
☐ Exploration

0001

Inspection Date: 1/12/99
Time: 8 :30 ☑am ☐pm to 1 :30 ☐am ☑pm
Date of Last Inspection: 12/28/98

Mine Name: Trail Mtn. County: Emery Permit Number: Act 015/009
Permittee and/or Operator's Name: PacifiCorp
Business Address: P.O. Box 1005, Huntington, UT 84528
Type of Mining Activity: ☑ Underground ☐ Surface ☐ Prep. Plant ☐ Other
State Officials(s): Bill Malencik
Company Official(s): Dennis Oakley
Federal Official(s): N/A
Weather Conditions: Pt. Cloudy, Stuff Off Snow At Mine
Existing Acreage: Permitted-4178 Disturbed-107 Regraded-_____ Seeded-_____ Bonded-107
Increased/Decreased: Permitted-_____ Disturbed-_____ Regraded-_____ Seeded-_____ Bonded-_____
Status: ☐ Exploration / ☑ Active / ☐ Inactive / ☐ Temporary Cessation / ☐ Bond Forfeiture
☐ Reclamation (☐ Phase I / ☐ Phase II / ☐ Final Bond Release / ☐ Liability_____Year)

## REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions
1. Substantiate the elements on this inspection by checking the appropriate performance standard.
   a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
   b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

| | EVALUATED | N/A | COMMENTS | NOV/ENF |
|---|---|---|---|---|
| 1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE | ☐ | ☐ | ☐ | ☐ |
| 2. SIGNS AND MARKERS | ☑ | ☐ | ☐ | ☐ |
| 3. TOPSOIL | ☑ | ☐ | ☑ | ☐ |
| 4. HYDROLOGIC BALANCE: | | | | |
| a. DIVERSIONS | ☑ | ☐ | ☑ | ☐ |
| b. SEDIMENT PONDS AND IMPOUNDMENTS | ☑ | ☐ | ☑ | ☐ |
| c. OTHER SEDIMENT CONTROL MEASURES | ☑ | ☐ | ☑ | ☐ |
| d. WATER MONITORING | ☐ | ☐ | ☐ | ☐ |
| e. EFFLUENT LIMITATIONS | ☐ | ☐ | ☐ | ☐ |
| 5. EXPLOSIVES | ☑ | ☐ | ☐ | ☐ |
| 6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES | ☐ | ☐ | ☐ | ☐ |
| 7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS | ☐ | ☐ | ☐ | ☐ |
| 8. NONCOAL WASTE | ☑ | ☐ | ☑ | ☐ |
| 9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES | ☑ | ☐ | ☑ | ☐ |
| 10. SLIDES AND OTHER DAMAGE | ☐ | ☐ | ☐ | ☐ |
| 11. CONTEMPORANEOUS RECLAMATION | ☐ | ☐ | ☐ | ☐ |
| 12. BACKFILLING AND GRADING | ☐ | ☐ | ☐ | ☐ |
| 13. REVEGETATION | ☐ | ☐ | ☐ | ☐ |
| 14. SUBSIDENCE CONTROL | ☐ | ☐ | ☐ | ☐ |
| 15. CESSATION OF OPERATIONS | ☐ | ☐ | ☐ | ☐ |
| 16. ROADS: | | | | |
| a. CONSTRUCTION/MAINTENANCE/SURFACING | ☑ | ☐ | ☐ | ☐ |
| b. DRAINAGE CONTROLS | ☑ | ☐ | ☐ | ☐ |
| 17. OTHER TRANSPORTATION FACILITIES | ☑ | ☐ | ☐ | ☐ |
| 18. SUPPORT FACILITIES/UTILITY INSTALLATIONS | ☑ | ☐ | ☐ | ☐ |
| 19. AVS CHECK (4th Quarter-April, May, June)_____(date) | ☐ | ☐ | ☐ | ☐ |
| 20. AIR QUALITY PERMIT | ☐ | ☐ | ☐ | ☐ |
| 21. BONDING & INSURANCE | ☐ | ☐ | ☐ | ☐ |

UTAH
NATURAL RESOURCES
Oil, Gas & Mining



## INSPECTION REPORT COMMENTS

Permit No. Act 015/009

Inspection Date 1/12/99.

Please number comments to correspond with topics on previous page.

General Comments. Dennis Oakley and the surface foreman accompanied the undersigned on this inspection. The surface foreman replaces Mr Carlson. Mr Oakley made arrangements for the surface foreman to attend the inspection.

The inspection started with a brief black board session where ideas were exchanged. This paved the way for a field inspection. Made a special effort to provide some additional background on the environmental control measures, past problems and strong points and things that the mine needs to do to keep the mine in compliance with the coal rules. Mr Oakley has been working very closely with the new surface foreman.

The mine and its environmental control measures were found to meet the performance standards.

Diversions Both disturbed and undisturbed diversions were observed. All ditches and culverts were open and functionable. During the inspection some paper cups.

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining



## INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 1/12/99

Please number comments to correspond with topics on previous page.

and small non-coal waste items were collected and placed in the non-coal waste storage area.

Sediment Pond Contained runoff, was not discharging and water level was about two feet below the decant level.

Siltfence. The siltfence around the topsoil pile was in place and no breaks in the siltfence was observed.

Fuel Storage Area. The permittee has a concrete containment and a sump on the fuel storage site. The used oil is stored in a metal tank outside of the aforementioned containment. Also, there was a fifty gallon drum that was stored outside the containment area. The used oil storage tank appeared to be made of heavy metal that would be difficult to rupture. However, this would not apply to the fifty gallon drum. Fluids of this nature should be protected by a berm to prevent a general spill and contine the fluids to the immediate area.

Suggested the permittee evaluate this storage area. Since mine equipment is being also fueled at this site

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining



## INSPECTION REPORT COMMENTS

Permit No. Act 015/009

Inspection Date 1/12/99

Please number comments to correspond with topics on previous page.

there is a concern that such tanks may be subject to being pinctured by equipment at the fuel site. Mr. Oakley stated he would discuss this matter with John Christensen. The day after the inspection was advised by Mr. Oakley that the 50 gallon drum had been confined to a safe area.

Non Coal Waste The surface foreman made a note and took immediate action to collect all the used auto/equipment batteries and ship them to central warehouse for collection and disposal.

Copy of report mailed to PC/ Dennis Oakley; OSM/Henry Austin; DOGM/ Joe Helfrich

Copy of report given to Price Field Office

Inspector's signature [signature] No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE