0030

RECEIVED
JUL 14 1986
DIVISION OF
OIL, GAS & MINING

CONSOL

Consolidation Coal Company
Emery Mine
P. O. Box 527
Emery, Utah 84522
(801) 286-2301

July 9, 1986

Mr. D. Wayne Hedberg
Division of Oil, Gas, and Mining
4241 State Office Building
Salt Lake City, Utah 84114

Re: Quarterly Pond Inspections
Emery Deep Mine
ACT/015/015

FILE COPY

Dear Mr. Hedberg,

The following is a summary of the quarterly pond inspections for the second quarter of 1986.

Pond #1 - (main mine sedimentation pond)

Date: 6/30/86
Time: 12:30 P.M.
Comments: The pond was discharging at this time with a staff gage reading of approximately 0.75. There were no visible signs of erosion, piping, or seepage. The embankment was in sound condition.

Pond #2 - (main mine yard sedimentation pond)

Date: 6/30/86
Time: 1:14 P.M.
comments: The pond was dry. There were no visible signs of erosion, piping, or seepage. The embankment was in sound condition. The outlet gate was in good working condition. The outlets and inlets were free of obstructions.

Pond #3 - (secondary mine yard sedimentation pond)

Date: 6/30/86
Time: 1:10 P.M.
Comments: The pond was dry. There were no visible signs of erosion, piping, or seepage. The embankment was in sound condition. The outlet gates were in good working condition. The inlets and outlets were free of any obstructions.

Pond #5 - (prep. plant sedimentation pond)

Date: 6/30/86
Time: 1:32 P.M.
Comments: The pond was dry. There were no visible signs of erosion, piping, or seepage. The embankment was in sound condition. The inlets and outlets were free of any obstructions.

R/O Lagoon

Date: 6/30/86
Time: 1:35 P.M.
Comments: There was approximately 8 inches of water standing over approximately one-half of the pond. There were no visible signs of erosion, piping, or seepage. The embankment was in sound condition. The recently seeded vegetation was coming up on the embankment. Various weeds are growing in the pond bottom.

Stephen C. Drummond

Stephen C. Drummond
M.S.H.A. Qualified
Impoundment Inspector