10-13-87 0004

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

File

inspection report

Permit No. ACT/015/015
Inspection Date 10-6-87

Permittee/Operator Name: Consolidation Coal Company
Business Address: P.O. Box 527
City: Emery State: Utah Zip: 84522
Mine: Emery Deep ☐ Surface ☑ Underground ☐ Other
County: Emery State: Utah
Company Official(s): Ron Thompson (Consol)
State Official(s): Holland Shepherd (DOGM)
Time of inspection 2:00 ☐ a.m. ☑ p.m. to 3:00 ☐ a.m. ☑ p.m. ☑ Partial ☐ Complete
Date of last inspection 9-2-87 Weather conditions: Sunny, Clear
Acreage 5180 ☐ Permitted 40 ☐ Disturbed 266 ☐ Regraded 266 ☑ Seeded 247 ☐ Bonded
Enforcement Action: Termination of N87-9-7-3 2 of 3

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☑	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☑	☐	☐	☑
— Other sediment control measures	☑	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☑	☐	☐	☑
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/015

Inspection Date 10-6-87

Please number comments to correspond with topics on previous page.

4.c. Sediment Ponds and Impoundments:

1. The operator has completed work on the inlet structures to Pond #5. The work appeared satisfactory so 1187-9-7-3, 2 of 3 was terminated. Alterations were made to the preexisting inlet structures to the degree which will require an admendment to the original plan design for pond #5. The operator will be surveying and developing new as-builts for the pond this month.

2. I asked the operator to remove some yard debris from the proximity of pond #2's diversion inlets. Pieces of scrap metal and wood have accumulated close to the diversions and may cause drainage blockages if left in place. Also, in relation to pond #2, I have asked the operator to reenforce a disturbed area drainage diversion to prevent piping from occurring. Any piping which may have occurred drained into the pond, and erosion is negligible, at this point.

15. Cessation of Operations:

The mine has resumed activity as of 9-14-87, and will remain active indefinitely.

Copy of report mailed to Given to Ron Thompson (Consol), Brian Smith (OSM)

Copy of report given to Joe Helfrich (DOGM)

Inspector's signature [signature] 10-6-87 No. #9

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

DOGM/IR-2

an equal opportunity employer

11/86 001049