0016

File ACT/015/015-89A
~~Permit~~
#2

RECEIVED
MAY 23 1989
DIVISION OF
OIL, GAS & MINING

Consolidation Coal Company
Emery Mine
P. O. Box 527
Emery, Utah 84522
(801) 286-2301

Ms. Susan Linner
Mineral Resource Development and
Reclamation Program
Utah Division of Oil, Gas & Mining
355 W. North Temple
3 Triad Center - Suite 350
Salt Lake City, Utah 84180-1203

May 22, 1989

RE: NOV N89-28-5-1, Permit 015/015

Dear Susan,

NOV N89-28-5-1 was issued to Consol for failure to prevent, to the extent possible, disturbance to a stream buffer zone. As of May 12, 1989, the stream bank has been cleaned to the extent possible using industrial vacuum equipment. The Price office was notified at that time and has since sent a representative to the site on inspection (May 16, 1989). The cleanup effort was approved by Darron Haddock at that time.

Part two of the NOV involves submitting a plan to minimize future disturbance to the area. As you are aware, the source of coal fines is our tipple, which is located in a severely restricted area in terms of space. It is impractical to remove the tipple to another location. We therefore propose to erect a "silt fence" at the location shown on Plate 3-2 (marked 39A). Research shows this to be an effective method of slowing air flow, which is our goal in controlling dust movement. Any dust escaping this system will be cleaned up when it accumulates to 2" thick.

Please contact me if you have any questions.

Respectfully,

Christopher M. Jones, P.E.
Project Engineer

Enc: Ch 3 Table of Contents
Ch 11 Table of Contents
Pg 3-52
Pgs 11-7 through 11-9
Plate 3-2