0005

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor

Ted Stewart
Executive Director

James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

INSPECTION REPORT

Partial: XXX Complete:__ Exploration:__
Inspection Date & Time: 7/1/96 / 7:00a.m.-2:00p.m.
Date of Last Inspection: 6/26/96

Mine Name: Emery Deep Mine County: Emery Permit Number: **ACT/015/015**
Permittee and/or Operator's Name: Consolidation Coal Company
Business Address: P.O. Box 527, Emery, Utah 84522
Type of Mining Activity: Underground XXX Surface__ Prep. Plant__ Other__
Company Official(s): Steve Behling
State Officials(s): Stephen J. Demczak Federal Official(s): None
Weather Conditions: Warm, 90's
Existing Acreage: Permitted- 5180 Disturbed- 40 Regraded- 2.7 Seeded- 2.7 Bonded-207
Increased/Decreased: Permitted-___ Disturbed-___ Regraded-___ Seeded-___ Bonded-___
Status: _Exploration/ XXX Active/__Inactive/__Temporary Cessation/__Bond Forfeiture
Reclamation (__Phase I/__Phase II/__Final Bond Release/__Liability_____Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions
1. Substantiate the elements on this inspection by checking the appropriate performance standard.
   a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
   b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[ ]	[ ]	[ ]	[ ]
2.	SIGNS AND MARKERS	[XX]	[ ]	[XX]	[ ]
3.	TOPSOIL	[XX]	[ ]	[XX]	[ ]
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[XX]	[ ]	[XX]	[ ]
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[XX]	[ ]	[XX]	[ ]
c.	OTHER SEDIMENT CONTROL MEASURES	[ ]	[ ]	[ ]	[ ]
d.	WATER MONITORING	[ ]	[ ]	[ ]	[ ]
e.	EFFLUENT LIMITATIONS	[ ]	[ ]	[ ]	[ ]
5.	EXPLOSIVES	[ ]	[ ]	[ ]	[ ]
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[ ]	[ ]	[ ]	[ ]
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[ ]	[ ]	[ ]	[ ]
8.	NONCOAL WASTE	[ ]	[ ]	[ ]	[ ]
9.	PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[ ]	[ ]	[ ]	[ ]
10.	SLIDES AND OTHER DAMAGE	[ ]	[ ]	[ ]	[ ]
11.	CONTEMPORANEOUS RECLAMATION	[ ]	[ ]	[ ]	[ ]
12.	BACKFILLING AND GRADING	[ ]	[ ]	[ ]	[ ]
13.	REVEGETATION	[ ]	[ ]	[ ]	[ ]
14.	SUBSIDENCE CONTROL	[ ]	[ ]	[ ]	[ ]
15.	CESSATION OF OPERATIONS	[ ]	[ ]	[ ]	[ ]
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[ ]	[ ]	[ ]	[ ]
b.	DRAINAGE CONTROLS	[ ]	[ ]	[ ]	[ ]
17.	OTHER TRANSPORTATION FACILITIES	[ ]	[ ]	[ ]	[ ]
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[ ]	[ ]	[ ]	[ ]
19.	AVS CHECK (4th Quarter-April, May, June)_____(date)	[ ]	[ ]	[ ]	[ ]
20.	AIR QUALITY PERMIT	[ ]	[ ]	[ ]	[ ]
21.	BONDING & INSURANCE	[ ]	[ ]	[ ]	[ ]

INSPECTION REPORT
(Continuation sheet)

PERMIT NUMBER: **ACT/015/015**

DATE OF INSPECTION: 7/1/96

(Comments are Numbered to Correspond with Topics Listed Above)

2. SIGNS AND MARKERS -

The identification signs were inspected and complied with the R645 regulations. The signs are placed at the mine property access from public roads.

3. TOPSOIL PILES -

The topsoil piles were protected by berms with some vegetation on the topsoil. There were no signs of erosion of the piles.

4A. DIVERSIONS -

The diversions throughout the property were spot-checked. There were no signs of breaching or erosion of the diversions. Several ditches and culverts were recently cleaned out.

4B. SEDIMENT PONDS AND IMPOUNDMENTS -

The sediment ponds were inspected with no hazardous conditions noticed. There were no signs of erosion of inlets, outlets or embankments. Two of the ponds were discharging as designed.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Consolidation Coal Company Marcia Petta (OSM)
Given to: Joe Helfrich (DOGM) Filed to: Price Field Office
Date: July 18, 1996

Inspector's Signature: #39
Stephen J. Demezak