0007

Consolidation Coal Company
Western Non-Mining Operations
Emery Mine
P.O. Box 527
Emery, Utah 84522
(801) 286-2301
Fax: (801) 286-2338

Mr. Daron R. Haddock
Permit Supervisor
Division of Oil, Gas, and Mining
1594 West North Temple, Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801

31 March 2000

Incoming
ACT/015/015

RE: Emery Temp. Coal Stockpile Inspection Report

Dear Mr. Haddock:

Enclosed is the 1st Qtr. Inspection Form of the Temp. Coal Stockpile, where the waste rock is being stored, at the Emery Mine. The form has been certified by a registered P.E. from our Sessor office.

If you have any questions please call me at (435) 286-2301.

Sincerely,

Stephen R. Behling

Stephen R. Behling
General Mine Foreman
Emery Mine

attachments: Inspection Form certified by a P.E.

RECEIVED
APR 03 2000
DIVISION OF
OIL, GAS AND MINING

INSPECTION FORM

COAL REFUSE PILES AND COAL WASTE IMPOUNDMENTS

Name STEPHEN R. BEHLING Title GENERAL MINE FOREMAN

Date 3-17-00 Date last inspected 12-2-99

Site Name EMERY TEMP. COAL STOCKPILE Mine Name EMERY

Refuse Facility ID # 1211-UT-09-00079-01

Refuse piles---Part A only
Impoundments---Part A and Part B

BDB 3/28/00

Part A

				N/A
1.	Foundation preparation (vegetation, topsoil removal?)	✓ Yes	___ No	
2.	Lift Thickness (inches) NO NEW CONSTRUCTION			
3.	Compaction (4 to 6 complete passes)	___ Yes	✓ No	
4.	Burning* (specify extent and location)	___ Yes	✓ No	
5.	Angle of Slope (degrees)	N/A	___	
6.	Seepage* (specify location, color, & appr. volume	___ Yes	✓ No	
7.	Cracks or scarps* (location, size)	___ Yes	✓ No	
8.	Major erosion problems* (location and extent)	___ Yes	✓ No	
9.	Water impounding against toe*	___ Yes	✓ No	

Part B

10.	Embankment freeboard (feet)		
11.	___Increase___Decrease in water level (feet)	___ Yes	___ No
12.	Sumps or sinkholes in slurry surface	___ Yes	___ No
13.	Clogging* (pipes, ditches, spillway)	___ Yes	___ No
14.	Trash racks clear and in place	___ Yes	___ No

* Adverse conditions noted in these items should be described (extent, location, volume, etc.) in the space provided. Major adverse changes could cause instability.

Inspection Category	Comments
	NO PROBLEMS WERE OBSERVED - NO HAZARDOUS CONDITIONS WERE FOUND.

BRIAN BUTTS
062-045024
REGISTERED PROFESSIONAL ENGINEER
STATE OF UTAH

Brian Butts
3/28/00

RECEIVED
APR 03 2000
DIVISION OF OIL, GAS AND MINING

FORM 1