0004

Ok

Consolidation Coal Company
Western Non-Mining Operations
Emery Mine
P.O. Box 527
Emery, Utah 84522
(801) 286-2301
Fax: (801) 286-2338

Mr. Daron R. Haddock
Permit Supervisor
Division of Oil, Gas, and Mining
1594 West North Temple, Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801

15 January 2002

Incoming
C/015/015

RE: Emery Temp. Coal Stockpile Inspection Report

Dear Mr. Haddock:

Enclosed is the 4th Qtr. Inspection Form of the Temp. Coal Stockpile, where the waste rock is being stored, at the Emery Mine. The form has been certified by a registered P.E. from our Sessor office.

If you have any questions please call me at (435) 286-2301.

Sincerely,

Stephen R. Behling

Stephen R. Behling
General Mine Foreman
Emery Mine

attachments: Inspection Form certified by a P.E.

INSPECTION FORM

COAL REFUSE PILES AND COAL WASTE IMPOUNDMENTS

Name Stephen R. Behling Title General Mine Foreman

Date 12-14-01 Date last inspected 9-11-01

Site Name Emery Temp. Coal Stockpile Mine Name Emery

Refuse Facility ID # 1211-UT-09-00079-01

Refuse piles---Part A only
Impoundments---Part A and Part B

Part A

1. Foundation preparation (vegetation, topsoil removal?)---- ___Yes N/A No
2. Lift Thickness (inches)---------- NO NEW CONSTRUCTION
3. Compaction (4 to 6 complete passes)---------- ___Yes ✓ No
4. Burning* (specify extent and location)---------- ___Yes ✓ No
5. Angle of Slope (degrees)---------- N/A
6. Seepage* (specify location, color, & appr. volume-------- ___Yes ✓ No
7. Cracks or scarps* (location, size)---------- ___Yes ✓ No
8. Major erosion problems* (location and extent)---------- ___Yes ✓ No
9. Water impounding against toe* ---------- ___Yes ✓ No

Part B

10. Embankment freeboard (feet)----------
11. ____Increase____Decrease in water level (feet)---------- ___Yes ___No
12. Sumps or sinkholes in slurry surface---------- ___Yes ___No
13. Clogging* (pipes, ditches, spillway)---------- ___Yes ___No
14. Trash racks clear and in place---------- ___Yes ___No

* Adverse conditions noted in these items should be described (extent, location, volume, etc.) in the space provided. Major adverse changes could cause instability.

Inspection Category	Comments
	NO problems observed - NO HAZARDOUS CONDITIONS were found - FEW SMALL RILLS SMOOTHED OUT

BRIAN BUTTS 062-045294 REGISTERED PROFESSIONAL ENGINEER STATE OF ILLINOIS

FORM 1