0008

United States Department of the Interior
OFFICE OF SURFACE MINING
Reclamation and Enforcement
[redacted] Brooks Towers
1020-15th Street
DENVER, COLORADO 80202

R Rpt to
ph Doug &
Joe

February 25, 1980

RECEIVED
FEB 27 1980
DIVISION OF
OIL, GAS & MINING

Mr. Ron Daniels
Coordinator of Mined Land Development
Department of Natural Resources
1588 North West Temple
Salt Lake City, Utah 84116

Dear Mr. Daniels:

Enclosed please find copies of on-site inspection reports. The inspections were conducted within Des-Bee-Dove Mine (Church) during the period of January 9, 1980.

If you have any questions or problems, please contact this office.

Sincerely,

Murray T. Smith
Chief, Division of Inspection & Enforcement

REGION V ON SITE INSPECTION REPORT

UTAH POWER & LIGHT COMPANY
DES-BEE-DOVE MINE (CHURCH)
OPERATOR: EMERY MINING CORPORATION
P.O. Box 899
Salt Lake City, Utah 84110
(801) 350-3535

DATE:	January 9, 1980
TIME:	1:45 p.m.
WEATHER:	Overcast and snowing
COUNTY & STATE:	Emery County, Utah
COMPANY OFFICIALS:	Kay Truman
STATE OFFICIALS:	Joe Helfrich and Doug Stewart
OSM OFFICIALS:	Ron Gregg and Vernon Maldonado
STATE PERMIT NO:	ACT-015-017
MSHA I.D. NUMBERS:	Little Dove 42-01393, Deseret 42-00988, and Beehive 42-00082

GENERAL COMMENTS

This inspection was conducted as a follow-up to check abatement of Notice of Violation #79-5-7-5 (NOV), issued on November 6, 1979. Both of the violations of this NOV were satisfactorily abated; therefore, terminations were issued. Due to a heavy snow cover on the ground and poor visability, a thorough inspection was impossible.

COMPLIANCE WITH INTERIM REGULATIONS

717.11 General Obligations

The mine is operating under a 211 plan, which was approved by the U.S. Geological Survey (USGS) in June 1978 and by the Utah Oil, Gas, and Mining Division in May 1978. The plan is presently at the minesite; therefore, Violation No. 2 of NOV #79-5-7-5 was terminated.

717.17 Protection of the Hydrologic System

Violation No. 1 of NOV #79-5-7-5 was terminated as a concrete berm has been installed, which prevented runoff from leaving the parking area and eroding the downslope. The concrete berm was well constructed and should prevent future runoff problems at this area.

SUMMARY

State Violations - Revegetation of disturbed downslopes being required. (Fall 1979)

OSM NOV's - All violations were terminated on January 9, 1980 and no new NOV's were issued.

Ron Gregg

RON GREGG
RECLAMATION SPECIALIST