0006

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

pgl

inspection report

Permit No. ACT/015/017

Inspection Date 10/25/90 & 10/31/90

Permittee/Operator Name PacifiCorp. Electric Operations (UP&L)

Business Address P.O. Box 310

City Huntington State Ut Zip 84528

Mine Des Bel Dove ☐ Surface ☒ Underground ☐ Other

County Emery State Ut

Company Official(s) Guy Davis

State Official(s) Bill Malencik & Steve Demczak

Time of inspection Records 10:00 ☒ a.m. ☐ p.m. to ___:___ ☐ a.m. ☐ p.m. ☐ Partial ☒ Complete

Date of last inspection Field 7/26/90 Weather conditions Clear & Warm

Acreage 2847 ☐ Permitted 74.5 ☐ Disturbed ☐ Regraded ☐ Seeded 74.5 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☒
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☒	☐	☐	☒
— Effluent limitations	☒	☐	☐	☒
5. Explosives	☒	☐	☐	☐
6. Development waste and spoil disposal	☒	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☒	☐	☐	☒
11. Contemporaneous reclamation	☒	☐	☐	☐
12. Backfilling and grading	☒	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☒	☐	☐	☐
15. Cessation of operations	☒	☐	☐	☐
16. Roads				
— Construction	☒	☐	☐	☐
— Drainage controls	☒	☐	☐	☐
— Surfacing	☒	☐	☐	☐
— Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☒	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/017

Inspection Date 10/25/90 & 10/31/90

Please number comments to correspond with topics on previous page.

General Comments. The operator technical group were in an office move. The inspection covered the records and then the field portion.

Records

- Permit expired 8/14/90. Since the operator permit was not timely renewed, the Division issue an enforcement action (CO#-C90-20-2-1) which included a schedule for upgrading required information.
- UPDES permit issued 2/11/88. Required reports have been completed and submitted to responsible agencies.
- Insurance Certificate was of record and dated 12/24/89.
- Sediment Pond Inspection reports had been completed for the first, second & third quarters were dated 3/28/90, 6/31/90, & 9/26/90.
- As built certifications had been completed and dated as follows:

  Sediment Pond: 11/16/89

  Haul Road 8/9/84
- Water monitoring records were reviewed and no problems noted.[a]
- Operator has a special use permit to utilize a USFS road from the cattle guard to the operators gate.

a/ Water samples had been taken up to and including the month of September. Some stations require monthly monitoring while others are quarterly.

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/017

Inspection Date 10/25 & 10/31/90

Please number comments to correspond with topics on previous page.

Field Portion

The mine continues in temporary cessation. The gate at the end of the public road is locked to prevent access to the mine.

Signs & Markers With the name change to Pacific Corp Electric Co., the operator advised me that they had ordered new signs for the proposed name change which has not yet been finalized as related to internal records.

Stream Channel Diversion The half round on the lower mine pad was checked for rodent and piping holes. None were found.

Diversions. The diversion by the fenced storage pad while functional should be cleaned where the ditch flattens out.

Sediment Pond Sediment pond contained water about a foot below the decant/oil skimmer. Pond was stable. Operator had done some rill erosion work on the slope of the pond.

Other Sediment Control Silt fences adjacent to the sediment pond should be cleaned before winter as a preventative measure to better handle the spring runoff.

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/017

Inspection Date 10/25 & 10/31/90

Please number comments to correspond with topics on previous page.

Roads

Some rocks had encroached and rolled on to a short segement of the haul road above the sediment pond. While such rocks did not impeed vehicle traffic, the undersigned asked the operator to remove the rocks & debris from the road.

The rocks from the slide still block a portion of the road to the upper pad. However vehicle passage is no problem for pickup size vehicle. The road above the slide needs some minor drainage control.

Copy of report mailed to PCEO/Guy Davis; OSM/Brain Smith; DOGM/Joe Helfrich

Copy of report given to filed PFO

Inspector's signature [signature] No. 26

11/2/90

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE-OPERATOR GOLDENROD – NOV FILE