.0021

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

page

inspection report

Permit No. INA/015/017
Inspection Date May 1, 1990

Permittee/Operator Name Utah Power & Light Mining Division
Business Address P.O. Box 310
City Huntington State Ut Zip 84528
Mine Des Bee Dove ☐ Surface ☒ Underground ☐ Other
County Emery State Ut
Company Official(s) Guy Davis
State Official(s) Bill Malencak & Susan White
Time of inspection 8:00 ☒ a.m. ☐ p.m. to 11:30 ☒ a.m. ☐ p.m. ☐ Partial ☒ Complete
Date of last inspection 1/18/90 Weather conditions Clear/Warm/Windy
Acreage 2847 ☐ Permitted 74.5 ☐ Disturbed ☐ Regraded ☐ Seeded 74.5 ☐ Bonded
Enforcement Action None
← Followup Items Suggested By Undersigned

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☒	☐	☐	☒
— Effluent limitations	☒	☐	☐	☒
5. Explosives	☒	☐	☐	☐
6. Development waste and spoil disposal	☒	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☒
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☒	☐	☐	☒
11. Contemporaneous reclamation	☒	☐	☐	☐
12. Backfilling and grading	☐	☐	☒	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☒	☐	☐	☒
15. Cessation of operations	☒	☐	☐	☒
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☒	☐	☐	☒
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

INSPECTION REPORT COMMENTS

Permit No. INA/015/017

Inspection Date May 1, 1990

Please number comments to correspond with topics on previous page.

General Comments. The undersigned was accompanied on the instant inspection by Division employee Susan White and Guy Davis representing the operator.

Records Review. The permit was on file and expires August 28, 1990. The operator is currently working on a permit renewal.

Other records on file and reviewed included the bond, liability insurance and pond and road "as constructed"-certifications. Also, water monitoring waste rock and UPDES records were observed. The operator stated that the subsidence field work had been completed, but to the best of his recollection a final report had not been submitted. The annual report has been submitted; however, the subsidence and hydrologic has not been submitted to date. In the interim, if such reports have not been submitted, please notify the division (Ms. Pam Griffin Grubaugh) when the reports will be submitted.

Divisions. Divisions were checked and no problems noted. The diversion into the sediment pond that exits the half-round

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

INSPECTION REPORT COMMENTS

Permit No. INA/015/017

Inspection Date 5/1/90

Please number comments to correspond with topics on previous page.

had recently been cleaned.

Sediment Pond. Sediment pond was about 2/3 full, was not discharging and appeared stable.

Other Sediment Control. Sediment control measures were field checked. One of the silt fences below the sediment pond, while still in compliance has reached a sediment level where a cleaning at this time would be in the interest of good environmental management.

Slides. The rock slide previously reported to the Division and also noted in an inspection report still remains on the road above the portal. The operator stated that other large rocks in the area are considered to be a safety hazard in as much as blasting would dislodge other rocks off the highwall. A large rock completely blocks the road to vehicle travel. Request that the operator provide additional feedback to the permit supervisor when the road is expected to be opened to vehicle traffic.

Revegetation. The test plots above the sediment pond was checked.

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/017

Inspection Date 5/1/90

Please number comments to correspond with topics on previous page.

Some planted seedlings have emerged. The area is extremely dry and the outlook in my opinion is not good. No rills were observed on the test plots.

Roads. Road were well maintained with drainage controls in place and fully functional.

The operator should consider as an item associated with the current permit review, to review the operators roads and how they interface with the county and USFS roads.

Other. The outslope on the middle pad requires some followup work ie. (1) remove 1 piece of metal sheeting from the outslope below the shop and (2) rills on the lower aforementioned outslope are approaching 9" in depth. Relative to the rills it was suggested the operator place a water bar above the rills as soon as possible. Further, that the rills be seeded and provided additional protection this fall.

Copy of report mailed to UP&L/Guy Davis SLC: OSM/Brian Smith, DOGM/Joe Helfrich & Susan White

Copy of report ~~given to~~ filed PFO

Inspector's signature [signature] No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

5/8/90

DOGM/IR-2 an equal opportunity employer 11/86 001049