0007

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gch pgl

inspection report

Permit No. Act 015/017
Inspection Date July 8/9, 1992

Permittee/Operator Name PacifiCorp Electric Operations
Business Address P.O. Box 1005
City Huntington State Ut Zip 84528
Mine Des Bee Dove ☐ Surface ☐ Underground ☐ Other
County Emery State Ut
Company Official(s) Karl Housekeeper
State Official(s) Bill Malencik
Time of inspection 8:30 8:00 X ☒ a.m. ☐ p.m. to 11:30 4:00 X ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete
Date of last inspection 4/9-10/92 Weather conditions Clear / 70s
Acreage 2847 ☐ Permitted 78 ☐ Disturbed ☐ Regraded ☐ Seeded 78 ☐ Bonded
Enforcement Action

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☒	☐	☐	☐
— Effluent limitations	☒	☐	☐	☐
5. Explosives	☐	☐	☒	☒
6. Development waste and spoil disposal	☐	☐	☒	☒
7. Coal processing waste	☐	☐	☒	☒
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☒	☐	☐	☐
11. Contemporaneous reclamation	☒	☐	☐	☐
12. Backfilling and grading	☒	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☒	☐	☐	☐
15. Cessation of operations	☒	☐	☐	☒
16. Roads				
— Construction	☒	☐	☐	☐
— Drainage controls	☒	☐	☐	☐
— Surfacing	☒	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☒	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☐
19 AVS check	☒	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

INSPECTION REPORT COMMENTS

Permit No. Act/015/017

Inspection Date July 8/9, 1992
Revised 7/28/92
Revision underscored.

Please number comments to correspond with topics on previous page.

General Comments The mine is in temporary cessation. As a result thereof no explosives are currently stored and/or used on site, no coal is being mine, all the belt lines have been cut going into the portals and no coal or non-coal waste is being generated. Non coal waste and materials that are stored on the shop storage area at times, i.e., small items are wind blown over the pad. The operator has been picking up such items as evidenced by items in the dumpster.

The permittee is reviewing the map showing pre SMCRA structures and post SMCRA structures and the PAP text on existing structures.

Signs & Markers. All signs and markers as required are in place. The permittee stated some additional markers are going to be added even though existing markers are visible i.e., one marker to another.

Soil pile. Soil storage adjacent to the sediment pond was observed together with protection measures. Vegetation on the pile is sparce, but the soil is protected by a ditch with straw bales to prevent any off site soil loss.

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act/015/017

Inspection Date

Please number comments to correspond with topics on previous page.

Diversions. Culverts, drop drains, ditches and berms were checked. All diversions held up in spite of the recent rains. Even the area previously repaired adjacent to the half-round culvert was stable.

Sediment Pond. Pond contained runoff. The water level was approximately 5 feet below the decant pipe. No problems were noted in the field.

Sediment pond records were reviewed and found in order ie, Sediment pond as constructed drawing 11/16/89, 2nd inspection 6/29/92, and annual report 12/31/91.

Other Sediment Control. The siltfences/straw bales at the mine site & pumphouse were fully functioning and no need of routine or preventative maintenance.

The contour furrows on the upper haul road pad all had water and no evidence that any runoff had discharged over the outslope.

The siltfences below the pond and adjacent to the pond access road needs to be cleaned.

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act/015/017

Inspection Date July 8 & 9, 1992

Please number comments to correspond with topics on previous page.

Refuse Pile The refuse pile was inspected and other than issues pending resolution itemized in the Division Order no problems were noted.

The refuse pond had about 2' of water in lower portion of the pond.

Refuse pile inspection for the first quarter was completed 4/8/92, survey notes for the second quarter were of record but the formal report had not yet been completed.

Required certifications were on file and depicted on a map.

Revegetation. Grass plants have become established mainly at the water line in the contour furrows mentioned above. The suspected source of the seed is from grass plants that have heretofore become established on the pad.

Copy of report mailed to PEO/Karl Houskeeper; OSM/Brian Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ Filed PFO

Inspector's signature Tim J Malencik No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

7/16/92