0001

December 5, 1982

Inspection Memo
to Coal File

RE: Utah Power & Light Company
Deer Creek Mine
ACT/015/018-A
Emery County, Utah

The above mentioned minesite was visited by Division Inspector David Lof on November 10, 1982. The purpose of the visit was to conduct a partial inspection and follow-up on NAOC 82-4-7-1. He was accompanied on the inspection by Larry Guymon of Emery Mining Corporation.

The buffer zone sign located above Deer Creek undisturbed drainage diversion inlet had not yet been moved. Once again, the need to move the sign was discussed and explained to the operator who promised to have the sign moved prior to the next monthly inspection.

During a September inspection at Deer Creek, the inspectors had issued NAOC 82-4-7-1 concerning the maintenance of the disturbed area runoff diversion system on the shop/warehouse/parking lot pad. At the time of this inspection there was approximately 4-6 inches of snow on the ground making it difficult to determine whether or not the inlets for the diversion system had been properly maintained and cleaned out. Mr. Guymon assured the inspector that they had finished reconnecting the system and cleaned it out by the end of October and that at that time the system was functioning as designed.

The realignment of the ROM conveyor and the conveyor from the tipple to the transfer point was discussed with Mr. Guymon. He said that plans for doing the realignment work were proceeding and that they expected to have the work completed within the next three months.

DAVID LOF
RECLAMATION OFFICER

DL/tck

cc: Tom Ehmett, OSM
Larry Guymon, Emery Mining Corporation

Statistics:

Vehicle: EX #45424 -- 396 miles
Per diem: 1 person X 1 day, 13.5 hrs. = $50.78
Grant: A & E