File

0005

October 10, 1985

TO: Coal File, Inspection and Enforcement Folder

FROM: Sandy Pruitt, Mining Field Specialist

RE: Deer Creek Mine, Utah Power & Light Company, ACT/015/018, Folder #7, Emery County, Utah

Sandy Pruitt conducted an inspection of the Deer Creek Mine, accompanied by Larry Guymon, Emery Mining Corporation (EMC), on October 8, 1985. Heavy snow showers were occurring at the time of this inspection.

All of the required abatement measures for NOV #N85-2-20-1 had been completed prior to this inspection for termination of the NOV. In addition to the required abatement for area #4 of the NOV (specifically, repair of the silt fence at the upper culvert crossing under the conveyor), EMC constructed a water bar beneath the conveyor, at the end of the conveyor access road, to collect conveyor drainage and divert it into the sediment pond. This reduces the volume of runoff that is treated at the silt fence cited in area #4 of NOV #N85-2-20-1.

No compliance problems were detected during this inspection.

dd

cc: Donna Griffin, OSM
Joe Helfrich, DOGM
Larry Guymon, EMC

Statistics: See Trail Mountain Mine memo dated October 10, 1985.

0347Q-19