0011

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

pgl gch

inspection report

Permit No. ACT/015/018
Inspection Date 10/23/90

Permittee/Operator Name Pacif Corp Electric Operation
Business Address P.O. Box 310
City Huntington State UT Zip 84528
Mine Deer Creek ☐ Surface ☑ Underground ☐ Other
County Emery State UT
Company Official(s) Guy Davis
State Official(s) Susan White
Time of inspection 10:30 ☒ a.m. ☐ p.m. to 2:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 9/7/90 Weather conditions Fair and cool
Acreage 14668 ☒ Permitted 560 ☐ Disturbed ☐ Regraded ☐ Seeded 560 ☒ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☑	☐	☐	☑
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☑	☐	☐	☑
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☑	☐	☐	☑
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/018

Inspection Date 10/23/90

Please number comments to correspond with topics on previous page.

13. The Pinyon-Juniper, Mixed Conifer and Riparian reference areas were located. All four corner stakes were in place. The Pinyon-Juniper reference area is located near the ventilation fan. Some damage to the vegetation is occuring due to the fines in the fan. No damage is yet seen in the reference area, however, damaged vegetation is adjacent to the boundries. This should be monitored.

4. The sediment pond was discharging

The mine is requesting to discharge mine water into Deer Crk.. ~~The~~ portions of the channel in the permit area were walked. Generally the channel bottom is wide and should be able to handle the proposed increased flows. However, serial bottle necks and exposed banks occur along the channel. Some type of armoring would be beneficial prior to increasing flows.

Copy of report mailed to Guy Davis/PCEO; Brian Smith/OSM

Copy of report given to Joe Helfrich/DOGM

Inspector's signature Susan M White No. 35

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE