0017

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/018

Inspection Date 7/11/90

Permittee/Operator Name UTAH POWER AND LIGHT

Business Address P.O. BOX 310

City HUNTINGTON State UTAH Zip

Mine DEER CREEK ☐ Surface ☒ Underground ☐ Other

County EMERY State UTAH

Company Official(s) GUY DAVIS

State Official(s) TOM MUNSON

Time of inspection 2:00 ☐ a.m. ☒ p.m. to 3:30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 6/13/90 Weather conditions SUNNY

Acreage 17668 ☒ Permitted 56 ☒ Disturbed ☐ Regraded ☐ Seeded 56 ☒ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
b — Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☐	☐	☐	☐
d — Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒ 1
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/018

Inspection Date 7/11/90

Please number comments to correspond with topics on previous page.

4b The culvert associated with the undisturbed diversion adjacent to the mine office was inspected and had accumulated enough silt to become a maintenance item. It will require that the operator use a hose and water to flush some of the silt out of the culvert. The operator said it would be taken care of. The capacity of the culvert was not unduly hindered.

4d) The following measures were implemented or maintained
1) a new silt fence at the Elk Canyon Coal Storage area
2) All the silt fence along the road had been cleaned
3) sediment traps were cleaned and functioning well.

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/018

Inspection Date 7/11/90

Please number comments to correspond with topics on previous page.

13. The ontslope to the Fan Access Road needs additional protection to prevent erosion (i.e. curlex blanket in rills with check dams). The rills were less than 9 inches but the area was in need of protection because of its steep slope and erosion potential.

Copy of report mailed to Brian Smith (OSM) GUY DAVIS (UP&L) BILL MALEREIK (DOGM

Copy of report given to JOE HELFRICH (DOGM

Inspector's signature Tom Munson No. 25

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer