0009

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. Act/015/018

Inspection Date August 11, 1992

Permittee/Operator Name PacifiCorp Electric Operations

Business Address P.O. Box 1005

City Huntington State Ut Zip 84528

Mine Deer Creek ☐ Surface ☒ Underground ☐ Other

County Emery State Ut

Company Official(s) Karl Houskeeper, John Christensen, Cindy Snow, Rachel Powell

State Official(s) Bill Malencik

Time of inspection 9:00 ☒ a.m. ☐ p.m. to 1:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 7/21/92 Weather conditions Clear/Warm/Dry Mine Site

Acreage 14668 ☐ Permitted 7.8 ☐ Disturbed ☐ Regraded ☐ Seeded 78 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☑	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☑	☐	☐	☐
— Diversions	☑	☐	☐	☑
— Sediment ponds and impoundments	☑	☐	☐	☑
— Other sediment control measures	☑	☐	☐	☑
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☑	☐	☐	☐
8. Noncoal waste	☑	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☑	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☑	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☑	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act/015/018

Inspection Date August 11, 1992

Please number comments to correspond with topics on previous page.

A partial inspection was conducted by the undersigned in the presence of company officials mentioned on page 1 of this report.

Items listed herein are not compliance issues at this time, but over time may develop into potential problems:

(1) Berm separating Deer Creek fan disturbed area from the undisturbed spring diversion. The height of the berm needs to be increased adjacent to undisturbed culvert outlet. This work was completed before the inspection closeout.

(2) Drop drains adjacent to the road guard rails and lying between the main pad and crusher stations. Rocks have started to encroach on the grates.

(3) All silt fences were observed. On the waste rock silt fence a minor problem may develop over time. An area about 6" x 6" lying above the silt fence is unstable. It may develop into a piping hole and possibly undercut the silt fence. The area in question lies about 50 feet from the interior T. B sign.

The permittee cleaned the weir at the sediment pond outlet as was suggested in the previous report

Copy of report mailed to PEO/Karl Houskeeper; OSM/Brent Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed PEO

Inspector's signature Tom J. Malencik No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

8/14/92