9-10-87

0020

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/019

Inspection Date 28 August 1987

Permittee/Operator Name Utah Power + Light / Mining Division

Business Address P.O. Box 310

City Huntington State UT Zip 84523

Mine Wilberg / Cottonwood ☐ Surface ☒ Underground ☐ Other

County Emery State

Company Official(s) Val Payne and Ray Christenson

State Official(s) Harold Sandbeck and Bill Malencik

Time of inspection 8.00 ☒ a.m. ☐ p.m. to 1:30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 5/13/87 Weather conditions Clear / Warm

Acreage 11508 ☒ Permitted 42.5 ☒ Disturbed ☐ Regraded ☐ Seeded 42.5 ☒ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☒	☐	☐	☐
b Diversions	☒	☐	☐	☒
c Sediment ponds and impoundments	☒	☐	☐	☒
d Other sediment control measures	☒	☐	☐	☒
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a Construction	☐	☐	☐	☐
b Drainage controls	☒	☐	☐	☐
c Surfacing	☐	☐	☐	☐
d Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/019

Inspection Date August 28, 1987

Please number comments to correspond with topics on previous page.

General Comments: This partial inspection concentrated on the hydrologic aspects of the mine site. Overall, the mine site appears well maintained. Road drainages were free of debris and were functional. The upper pad Wilberg fan row was inspected and found to be in excellent shape.

2.) Signs and Markers: The mine site was in compliance regarding signs and markers.

4.b.) Diversions: A diversion on upper storage pad near garbage ramp requires minor cleaning. East of the parking lot, a drainage and culvert needs cleaning as a preventive maintaince measure. A [redacted] 54 inch [redacted] culvert under the lower storage pad area requires preventive maintaince in the form of removing minor sediment buildup.

4.c.) Sediment Ponds and Impoundments: Lower pond was empty and inlet looks good. The upper pond contained water and appears functional. Both ponds are scheduled to be cleaned. The operator was currently cleaning the lower pond. While cleaning the pond, the operator will check the pond liner as a safeguard against possible future leakage.

4.d.) Other Sediment Control Measures: Strawbails at the left fork undisturbed grimes area needs preventive maintaince to continue providing erosion protection.

Copy of report mailed to Donna Griffin, OSM and Val Payne, UP&L

Copy of report given to Joe Helfrich, DOGM

Inspector's signature Harold D. Hanlin, 1 Sept. 1987 No. 27

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE