0014

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/019

Inspection Date 6/20/91

Permittee/Operator Name PACIFIC CORP. ELECTRIC OPERATIONS

Business Address BOX 310

City HUNTINGTON State UTAH Zip 84528

Mine COTTONWOOD/WILBERG ☐ Surface ☒ Underground ☐ Other

County EMERY State UT

Company Official(s) GUY DAVIS

State Official(s) TOM MUNSON

Time of inspection 2:00 ☐ a.m. ☒ p.m. to 4:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 5/13/91 Weather conditions SUNNY

Acreage 1532 ☐ Permitted 101.74 ☐ Disturbed ☐ Regraded ☐ Seeded 101.74 ☐ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
A Stream channel diversions	☑	☐	☐	☐
B Diversions	☑	☐	☐	☑
C Sediment ponds and impoundments	☑	☐	☐	☑
D Other sediment control measures	☑	☐	☐	☑
E Surface and groundwater monitoring	☐	☐	☐	☐
F Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☑	☐	☐	☑
12. Backfilling and grading	☑	☐	☐	☑
13. Revegetation	☑	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
– Construction	☐	☐	☐	☐
– Drainage controls	☐	☐	☐	☐
– Surfacing	☐	☐	☐	☐
– Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/019

Inspection Date 6/20/91

Please number comments to correspond with topics on previous page.

4b Diversions - All diversions associated with the New Waste Rock Facilities were well maintained. The diversion associated with the topsoil pile had been breached to access the pile but was immediately reconstructed

c. The sediment pond was dry and no evidence of discharge was noted.

d. The silt fence installations were in good repair and there was no evidence of suspended solids leaving the site

12. Backfilling and Grading - lift #1 was completed and the subsoil and topsoil had been applied. The waste rock base for lift #2 was being constructed. All work was being preformed according to plan.

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/019

Inspection Date 6/20/91

Please number comments to correspond with topics on previous page.

11. Contemporaneous Reclamation - All areas reseeded during the fall of 1990 at the Waste Rock Site have responded extremely well to the use of Erosion matting which used to protect the soil and seeds. The rough pock-marked areas have provided excellent microsites for seed germination. Revegetation test plots at the mine site show areas that have been watered as showing the greatest amount of vegetation response.

Copy of report mailed to Brian Smith OSM, GUY DAVIS, PACICORP

Copy of report given to JOE HELFRICH

Inspector's signature Tom Munson No. 25

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE