


SCALE: 1" = 400'

DATE: April 03, 2002

ACAD REFERENCE: *2001 SUMMARY*

UTAH REGISTERED PROFESSIONAL ENGINEER #191488 John Christopher Lewis

I hereby certify that the design and/or map contained herein was prepared by me or under my supervision and is true and correct to the best of my knowledge.

# Crandall Canyon Project
# Hiawatha Seam
# 2001 Production Areas

## LEGEND

| | | | |
|---|---|---|---|
| Longwall Gob Areas | | Jun. 2001 | Production Area |
| Jan. 2001 | Production Area | Jul. 2001 | Production Area |
| Feb. 2001 | Production Area | Aug. 2001 | Production Area |
| Mar. 2001 | Production Area | Sep. 2001 | Production Area |
| Apr. 2001 | Production Area | Oct. 2001 | Production Area |
| May 2001 | Production Area | Nov. 2001 | Production Area |
| | | Dec. 2001 | Production Area |


GENWAL RESOURCES, INC.
P.O. Box 1077
Price, Utah 84501
Telephone: (435) 564-4000 Fax: (435) 564-4002



RECEIVED
APR 05 2002
DIVISION OF OIL, GAS AND MINING


## TRESPASS AREA SUMMARY

1. This area of the Panel 6 Blinders was mined during November 1996 and January 1997 according to the revised R2P2 map dated October 1996. The Panel 6 area was mined out and sealed in June 1997.

2. In mid-1998 Genwal Resources Inc. retained the services of a Registered Land Surveyor to investigate BLM concerns that the location of the east property line in Section 1 had been improperly located on the approved October 1996 R2P2 map.

3. On September 22, 1998 the Registered Land Surveyor determined that the location of the eastern property line in Section 1 had been incorrectly located and certified the Broad property line as shown, which resulted in an intrusion trespass situation.

4. A trespass assessment was settled with the BLM on December 6, 1999. Genwal Resources Inc. paid the assessment on December 14, 1999. The Department of Oil, Gas, and Mining issued a Cessation Order (CO-99-39-1) on December 14, 1999, to which Genwal Resources Inc. immediately complied.