0010

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/041/002

Inspection Date June 6, 1990

Permittee/Operator Name Southern Utah Fuel Company

Business Address 397 So. 800 W.

City Salina State Utah Zip 84652

Mine Convulsion Canyon ☐ Surface ☒ Underground ☐ Other

County Sevier State Utah

Company Official(s) Mike Davis

State Official(s) Daron Haddock

Time of inspection 2:00 ☐ a.m. ☒ p.m. to 4:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection May 30, 1990 Weather conditions Mostly Sunny Warm

Acreage 17301 ☐ Permitted 24.3 ☐ Disturbed ☐ Regraded ☐ Seeded 67.8 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☐	☐	☐	☐
c Sediment ponds and impoundments	☒	☐	☐	☒
d Other sediment control measures	☒	☐	☐	☒
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☒	☐	☐	☒
7. Coal processing waste	☒	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/041/002

Inspection Date June 6, 1990

Please number comments to correspond with topics on previous page.

4c Sediment Ponds: The mine sediment pond was recently decanted. There appears to be plenty of storage capacity available at this time. The waste rock site sediment pond is dry and in good condition.
4d. Other sediment control: Silt fence has been recently installed in the diversion at the waste rock site. It appears that this will help prevent erosion of the channel where vegetation is sparse.
6. Development waste & spoil disposal: The first lift of rock waste has been completed and the second lift is now being put in place. Cover material has been placed on the 1st lift and a diversion put in to divert water from the waste pile. Rip-Rap is placed where required. Seeding of the pile will take place.
13. Revegetation. Various sites seeded last fall have sparse vegetation growing. This may be due to the extreme dry conditions. Areas of concern include - the slope above the new coal stock pile and the topsoil + subsoil piles at the rock waste site. Additional seeding may be considered.

Copy of report mailed to Brian Smith (OSM) Mike Davis (Sufco)

Copy of report given to Joe Helfrich DOGM.

Inspector's signature Daron R. Haddock No. 28

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE