0052

Canyon Fuel Company, LLC
SUFCO Mine
397 South 800 West
Salina, Utah 84654
(435) 286-4880 Fax: (435) 286-4499

June 29, 2000

Utah Coal Regulatory Program
Division of Oil, Gas and Mining
1594 West North Temple, Suite 1210
P. O. Box 145801
Salt Lake City, Utah 84114-5801

Jacoring
ACT/041/002

Dear Permit Supervisor:

Enclosed are copies of Canyon Fuel Company's - SUFCO Mine Quarterly Sediment Pond and Waste Rock Disposal inspection reports conducted on June 29, 2000.

Sincerely,
CANYON FUEL COMPANY, LLC
SUFCO Mine

Michael L Davis

Michael L. Davis
Environmental & Construction Supervisor

MLD:kb

Encl.

cc: DOGM - Sediment Pond Inspection File

P:\GOVT2000\DOGMCORR\SEDPNDRW2QT.DOC

RECEIVED
JUL 13 2000
DIVISION OF
OIL, GAS AND MINING

2-27-92 MLD

CANYON FUEL COMPANY - SUFCO MINE

Coal Refuse Piles Quarterly Inspection Report

Inspector Mike Davis Title Environ + Const Supervisor

Date 6-29-00 Permit # ACT/041/002

1. Foundation Preparation (vegetation, topsoil removal?) X Yes ___ No

2. Lift Thickness (inches) 14 – 20"

3. Compaction X Yes ___ No

4. Burning (specify extent and location) ___ Yes X No

None observed

5. Angle of Slope (degrees) 22-24°

6. Seepage (specify location, color, & appr. volume) ___ Yes X No

None observed

7. Cracks or Scarps (location and size) ___ Yes X No

None observed

8. Major Erosion Problems (location and extent) ___ Yes X No

None observed

9. Water Impounding Against Toe ___ Yes X No

10. Any appearance of instability, structural weakness or other hazardous conditions ___ Yes X No

No appearance of instability, structural weakness or other hazardous conditions were observed

Comments: Cable gate needs new lock. Trash on edge that was picked out needs to be hauled to minesite

Wesley K Sorensen

Wesley K. Sorensen, P.E.

Registration No. 159457

State of Utah

P:\WP1999\MLD\GEN\SEDPOND.FRM

2/27/92 MLD

CANYON FUEL COMPANY - SUFCO MINE

Rock Waste Sediment Pond Quarterly Inspection Report

Inspector Mike Davis Date 6-29-00

1. Dam Structural Weakness

A. Cracks or scarps on crest ___ Yes X No

None observed

B. Cracks or scarps on slope ___ Yes X No

None observed

C. Sloughing or bulging on slope ___ Yes X No

None observed

2. Major Erosion Problems ___ Yes X No

None observed

3. Surface Movements of Surrounding Slopes ___ Yes X No

None observed

4. Visible Sumps or Sinkholes in Slurry Surface ___ Yes X No

None observed - Sediment pond is dry

5. Clogging

A. Spillway channels and pipes ___ Yes X No

None observed

2/27/92 MLD

CANYON FUEL COMPANY - SUFCO MINE

Minesite Sediment Pond Quarterly Inspection Report

Inspector Mike Davis Date 6-29-00

1. Dam Structural Weakness

A. Cracks or scarps on crest ___ Yes X No

None observed

B. Cracks or scarps on slope ___ Yes X No

None observed

C. Sloughing or bulging on slope ___ Yes X No

None observed

2. Major Erosion Problems ___ Yes X No

No major erosion problems were observed. Minor old erosion on slope above pond

3. Surface Movements of Surrounding Slopes ___ Yes X No

None observed

4. Visible Sumps or Sinkholes in Slurry Surface ___ Yes X No

None observed

5. Clogging

A. Spillway channels and pipes ___ Yes X No

None observed