0032

041/002 Incoming
cc: Steve D. OK

Canyon Fuel Company, LLC
SUFCO Mine
397 South 800 West
Salina, UT 84654
(435) 286-4880 Fax: (435) 286-4499

RECEIVED
JUN 26 2002
DIVISION OF
OIL, GAS AND MINING

June 26, 2002

Utah Coal Regulatory Program
Division of Oil, Gas and Mining
1594 West North Temple, Suite 1210
P. O. Box 145801
Salt Lake City, Utah 84114-5801

Dear Permit Supervisor:

Enclosed are copies of Canyon Fuel Company's - SUFCO Mine Quarterly Sediment Pond and Waste Rock Disposal inspection reports conducted on June 24, 2002.

Sincerely,
CANYON FUEL COMPANY, LLC
SUFCO Mine

Michael L. Davis

Michael L. Davis
Environmental & Construction Supervisor

MLD:kb

Encl.

cc: DOGM - Sediment Pond Inspection File

SUFPUB\GOVT2002\DOGMCORR\SEDPNDRW2QT.DOC

2-27-92 MLD

CANYON FUEL COMPANY - SUFCO MINE

Coal Refuse Piles Quarterly Inspection Report

Inspector Michael Davis Title Env. & Construction Supervisor

Date 6-24-02 Permit # ACT/041/002

1. Foundation Preparation (vegetation, topsoil removal?) X Yes ___ No

2. Lift Thickness (inches) Waste material has just dried out enough to start mixing and compacting in lifts. This will be done in July

3. Compaction X Yes ___ No

4. Burning (specify extent and location) ___ Yes X No

5. Angle of Slope (degrees) 22-24°

6. Seepage (specify location, color, & appr. volume) ___ Yes X No

None observed

7. Cracks or Scarps (location and size) ___ Yes X No

None observed

8. Major Erosion Problems (location and extent) ___ Yes X No

None observed

9. Water Impounding Against Toe ___ Yes X No

None observed — Area dry

10. Any appearance of instability, structural weakness or other hazardous conditions ___ Yes X No

No appearance of instability or other hazardous conditions were observed

Clear — hot 70°F

Wesley K. Sorensen

Wesley K. Sorensen, P.E.

Registration No. 159457

State of Utah

RECEIVED

P:\WP1999\MLD\GEN\SEDPOND.FRM

2/27/92 MLD

CANYON FUEL COMPANY - SUFCO MINE

Rock Waste Sediment Pond Quarterly Inspection Report

Inspector Mike Davis Date 6-24-02

1. Dam Structural Weakness

A. Cracks or scarps on crest ___ Yes X No

None observed

B. Cracks or scarps on slope ___ Yes X No

C. Sloughing or bulging on slope ___ Yes X No

2. Major Erosion Problems ___ Yes X No

None observed

3. Surface Movements of Surrounding Slopes ___ Yes X No

None observed

4. Visible Sumps or Sinkholes in Slurry Surface ___ Yes X No

Pond was dry during inspection

5. Clogging

A. Spillway channels and pipes ___ Yes X No

None observed

B. Decant System ___ Yes X No

Decant system valve is closed and locked

C. Diversion ditches ___ Yes X No

None observed

6. Seepage (Specify Location, Color and Approx. Volume)

___ Yes X No

None observed

7. Any appearance of instability, structural weakness, or other hazardous conditions ___ Yes X No

None observed

8. Other Comments

Clear day - 70°F

Pond is dry

2/27/92 MLD

CANYON FUEL COMPANY - SUFCO MINE

Minesite Sediment Pond Quarterly Inspection Report

Inspector Mike Davis Date 6-24-02

1. Dam Structural Weakness

A. Cracks or scarps on crest ___ Yes X No

None observed

B. Cracks or scarps on slope ___ Yes X No

None observed

C. Sloughing or bulging on slope ___ Yes X No

None observed

2. Major Erosion Problems ___ Yes X No

None observed

3. Surface Movements of Surrounding Slopes ___ Yes X No

None observed

4. Visible Sumps or Sinkholes in Slurry Surface ___ Yes X No

None observed

5. Clogging

A. Spillway channels and pipes ___ Yes X No

Channels clear

RECEIVED
DIVISION OF
OIL, GAS & MINING

B. Decant System ___ Yes X No

Decant system closed + locked

C. Diversion ditches ___ Yes X No

None observed

6. Seepage (Specify Location, Color and Approx. Volume) ___ Yes X No

None observed

7. Any appearance of instability, structural weakness, or other hazardous conditions ___ Yes X No

No instability or hazardous conditions were observed

8. Weir level X Yes ___ No

9. Other Comments

Clear - 70°F