0005

Document Information Form

Mine Number: C/043/001

File Name: Incoming

To: DOGM

From:

Person N/A

Company N/A

Date Sent: NOV 28, 1978

Explanation:

REGION V ON-SITE INSPECTION

cc:

File in:
C/043/001, 1978, Incoming
Refer to:
- ☐ **Confidential**
- ☐ **Shelf**
- ☐ **Expandable**

Date _____ For additional information

0005

ACT/043/001

Copy to file

REGION V ON-SITE INSPECTION

UTAH COAL & ENERGY - BLACK HAWK MINE

RECEIVED
NOV 28 1978
DIVISION OF OIL, GAS, & MINING

DATE:	October 31, 1978
TIME:	4:30 P.M.
WEATHER:	Clear and cool
COUNTY & STATE:	Summit County, Utah
STATE OFFICIALS:	Ron Daniels and Mary Ann Wright
OSM OFFICIALS:	Murray T. Smith and Thomas E. Ehmett
INSPECTION TYPE:	Initial

GENERAL COMMENTS

This is an underground coal mine located in Summit County, Utah about 30 miles N.E. of Salt Lake Ciyt near Coalville, Utah. At the time of the inspection, the mine was inactive, no one from the company was present at the mine site.

The site consisted of two portals and surface facilities. A small stockpile of coal existed under the conveyor.

According to state officials, the requirement for the Black Hawk Mine to have a state permit has not been met. This is a violation of 30 USC § 502 (a).

COMPLIANCE WITH INTERIM REGULATIONS

717.12 Signs and Markers

A mine identification sign existed at the mine entrance. The sign, however, did not have all the required information since the state permit # was lacking (due to the fact that no state permit has been issued).

717.14 Backfilling and Grading

No backfilling or grading was evident at this site. It appears that the mine has not as of yet progressed that far.

Since no representative from the mine was present it was difficult to determine exactly what
the effective date of the Surface

Some of the areas above the porta
however. This was evident becaus
were obivously recently left.

?

File in:
- ☐ Confidential
- ☐ Shelf
- ☐ Expandable

Refer to Record No 0005 Date 11-28-78
In C/043/001, 1978, Incoming
For additional information

717.15 Disposal of Spoil and Waste

It was not apparent that spoil or waste material was being permanently disposed of at this site.

0005

ACT/043/001

Copy to file

REGION V ON-SITE INSPECTION

UTAH COAL & ENERGY - BLACK HAWK MINE

RECEIVED
NOV 28 1978
DIVISION OF OIL, GAS, & MINING

DATE:	October 31, 1978
TIME:	4:30 P.M.
WEATHER:	Clear and cool
COUNTY & STATE:	Summit County, Utah
STATE OFFICIALS:	Ron Daniels and Mary Ann Wright
OSM OFFICIALS:	Murray T. Smith and Thomas E. Ehmett
INSPECTION TYPE:	Initial

GENERAL COMMENTS

This is an underground coal mine located in Summit County, Utah about 30 miles N.E. of Salt Lake Ciyt near Coalville, Utah. At the time of the inspection, the mine was inactive, no one from the company was present at the mine site.

The site consisted of two portals and surface facilities. A small stockpile of coal existed under the conveyor.

According to state officials, the requirement for the Black Hawk Mine to have a state permit has not been met. This is a violation of 30 USC § 502 (a).

COMPLIANCE WITH INTERIM REGULATIONS

717.12 Signs and Markers

A mine identification sign existed at the mine entrance. The sign, however, did not have all the required information since the state permit # was lacking (due to the fact that no state permit has been issued).

717.14 Backfilling and Grading

No backfilling or grading was evident at this site. It appears that the mine has not as of yet progressed that far.

Since no representative from the mine was present it was difficult to determine exactly what area had been affected since the effective date of the Surface Mining and Reclamation Act.

Some of the areas above the portals had been affected recently however. This was evident because of the equipment tracks that were obivously recently left. ??

717.15 Disposal of Spoil and Waste

It was not apparent that spoil or waste material was being permanently disposed of at this site.

717.17 Water Quality Standards and Effluent Limitations

No sediment control and collection system existed at this site. This is a violation of 30 CFR 717.17. There were no sediment ponds and no drainage system on the access roads or surface facilities.

Erosion was evident at the access road bridge over the nearby stream.

No approved surface water monitoring plan exists at this site.

No approved ground water monitoring plan exists at this site.

All of the above are violations of 30 CFR 717.17.

717.18 Dams Constructed of Waste Material

None.

717.20 Topsoil Handling and Revegetation

Some roads have recently been constructed above the portal area. Equipment tracks were fresh. It was evident that the topsoil had not been salvaged prior to this surface disturbance. No topsoil stockpiles were present at the site. This is a violation of 30 CFR 717.20.

No revegetation was noted at the site.