0003

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

DRH
gch

INSPECTION REPORT

INSPECTION DATE & TIME: December 18, 1991
1:00 pm to 3:00 pm

Permittee and/or Operators Name: Summit Coal Company
Business Address: P.O. Box 646, Coalville, Utah 84017
Mine Name: Boyer Mine Permit Number: INA/043/008
Type of Mining Activity: Underground X Surface___ Other___
County: Summit
Company Official (s): None
State Official(s): David W. Darby
Partial: XX Complete:__ Date of Last Inspection: Nov. 9,1990
Weather Conditions: Cold, clear with snow on the ground
Acreage: Permitted 170 Disturbed 5.5 Regraded__ Seeded__ Bonded 5.5
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	( )	( )	(X)
2. SIGNS AND MARKERS	(X)	( )	( )	( )
3. TOPSOIL	(X)	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	(X)	( )	( )	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	( )	( )	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	(X)	( )	( )	(X)
f. EFFLUENT LIMITATIONS	(X)	( )	( )	(X)
5. EXPLOSIVES	( )	( )	(X)	( )
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	(X)	( )	( )	( )
8. NONCOAL WASTE	(X)	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	(X)	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	(X)	( )	( )	( )
12. BACKFILLING AND GRADING	(X)	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	(X)	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	(X)	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT

(continuation sheet) Page 2 of 2

PERMIT NUMBER: INA/043/008 DATE OF INSPECTION: 12-18-90

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permit

There has been no activity at the minesite since the portals were backfilled in October of 1990 (see October 17, 1990 inspection report).

4. Hydrologic Balance

During the portal backfilling process the contractor installed two large berms at the access sites to ensure runoff would not leave the minesite and to discourage public access. No runnoff had left the site and it appeared that no trespassing had occurred. There was no water in the sedimentation pond. The snow on the ground (approximately two feet) had not started to melt.

Copy of this Report:
Mailed to: Brian Smith-OSM, PFO
Given to: Daron Hadock-DOGM, Joe Helfrich-DOGM

Inspectors Signature & Number: Daron Daly #18 Date: 12-19-90