0011

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/043/008
Inspection Date Feb 26, 1992

Permittee/Operator Name Summit Coal Co.
Business Address P.O. Box 646, Coalville, Ut 84017
City _____ State _____ Zip _____
Mine Boyer Mine ☐ Surface ☒ Underground ☐ Other
County Summit State Utah
Company Official(s) None
State Official(s) Wayne H. Western
Time of inspection 11:00 ☒ a.m. ☐ p.m. to 12:30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 1/14/92 Weather conditions mild, sunny to overcast
Acreage 170 ☐ Permitted 5.5 ☐ Disturbed 0.0 ☐ Regraded 0.0 ☐ Seeded 5.5 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☒	☐	☐
— Diversions	☐	☒	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☐
— Other sediment control measures	☐	☒	☐	☐
— Surface and groundwater monitoring	☐	☐	☒	☐
— Effluent limitations	☐	☐	☒	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☒	☐	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☐	☒	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☒	☐	☐
10. Slides and other damage	☐	☐	☒	☐
11. Contemporaneous reclamation	☐	☐	☒	☐
12. Backfilling and grading	☒	☐	☐	☐
13. Revegetation	☐	☐	☒	☐
14. Subsidence control	☐	☐	☒	☐
15. Cessation of operations	☐	☒	☐	☐
16. Roads				
— Construction	☐	☐	☒	☐
— Drainage controls	☐	☒	☐	☐
— Surfacing	☐	☐	☒	☐
— Maintenance	☐	☐	☒	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☐	☐	☒	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. _____

Inspection Date _____

Please number comments to correspond with topics on previous page.

Some Straw bales that have been placed in stream channels are missing. Some straw bales have so much sedement deposited up stream that water can flow over the top of the bales.

There is some erosion occuring on the roads.

Copy of report mailed to Brain Smith, OSM

Copy of report given to Daron Haddock and Joe Helfrich DOGM

Inspector's signature Wayne H Western No. 42

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer