0013

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor

Ted Stewart
Executive Director

James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

INSPECTION REPORT

Partial: __ Complete: x Exploration: __
Inspection Date & Time: March 25, 1994 / 16:00-17:00
Date of Last Inspection: February 18, 1994

Mine Name: Boyer Mine County: Summit Permit Number: **INA /043/008**
Permittee and/or Operator's Name: Summit Coal Co.
Business Address: P.O. Box 646, Coalville, Utah 84017
Type of Mining Activity: Underground x Surface __ Prep. Plant __ Other __
State Officials(s): Wayne Western
Company Official(s): None Federal Official(s): None
Weather Conditions: Partly cloudy skies light winds and mild temperatures
Existing Acreage: Permitted- 170 Disturbed- 5.5 Regraded- 0 Seeded- 0 Bonded- 5.5
Increased/Decreased: Permitted-___ Disturbed-___ Regraded-___ Seeded-___ Bonded-__
Status: __Exploration/__Active/__Inactive/__Temporary Cessation/ x Bond Forfeiture
Reclamation (__Phase I/__Phase II/__Final Bond Release/__Liability_____Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions
1. Substantiate the elements on this inspection by checking the appropriate performance standard.
   a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
   b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[ ]	[x]	[ ]	[ ]
2. SIGNS AND MARKERS	[x]	[ ]	[ ]	[ ]
3. TOPSOIL	[ ]	[ ]	[ ]	[ ]
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	[x]	[ ]	[x]	[ ]
b. SEDIMENT PONDS AND IMPOUNDMENTS	[ ]	[ ]	[x]	[ ]
c. OTHER SEDIMENT CONTROL MEASURES	[ ]	[ ]	[ ]	[ ]
d. WATER MONITORING	[ ]	[x]	[ ]	[ ]
e. EFFLUENT LIMITATIONS	[ ]	[x]	[ ]	[ ]
5. EXPLOSIVES	[ ]	[x]	[ ]	[ ]
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[ ]	[ ]	[ ]	[ ]
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[x]	[ ]	[ ]	[ ]
8. NONCOAL WASTE	[x]	[ ]	[ ]	[ ]
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[x]	[ ]	[x]	[ ]
10. SLIDES AND OTHER DAMAGE	[x]	[ ]	[ ]	[ ]
11. CONTEMPORANEOUS RECLAMATION	[x]	[ ]	[ ]	[ ]
12. BACKFILLING AND GRADING	[x]	[ ]	[ ]	[ ]
13. REVEGETATION	[x]	[ ]	[ ]	[ ]
14. SUBSIDENCE CONTROL	[ ]	[x]	[ ]	[ ]
15. CESSATION OF OPERATIONS	[ ]	[x]	[ ]	[ ]
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	[x]	[ ]	[x]	[ ]
b. DRAINAGE CONTROLS	[x]	[ ]	[ ]	[ ]
17. OTHER TRANSPORTATION FACILITIES	[ ]	[x]	[ ]	[ ]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[x]	[ ]	[ ]	[ ]
19. AVS CHECK (4th Quarter-April, May, June)_____(date)	[ ]	[x]	[ ]	[ ]
20. AIR QUALITY PERMIT	[ ]	[x]	[ ]	[ ]
21. BONDING & INSURANCE	[ ]	[x]	[ ]	[ ]

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: ACT/043/008 DATE OF INSPECTION: March 25, 1994

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments:

Most of the snow had melted. The snow that was on the ground had been from a resent storm. The snow melt had made the site very muddy. In some areas I would sink 1 to 2 inches into the mud. There were no other footprints or signs that anyone had recently been on the site. There was nothing on the site that constituted an eminent harm to human safety or the environment.

Reclamation:

The Coal staff is developing the final reclamation plans. The plans should be completed by June 1994 and work should begin by October 1994.

4a. DIVERSIONS

The diversions were all free of ice and snow. Most of the snow melt had gone into the soil and there had been little surface flow.

4b. SEDIMENT PONDS AND IMPOUNDMENTS

The sediment pond had 1 foot of water. The inlet and emergency spillway to the pond were clear and functional.

9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES

There were no deer tracks on the site. There were 3 eagles that were soaring over the site and adjacent ground.

Copy of this Report:
Mailed to: Bernie Freeman (OSM)
Given to: Joe Helfrich (DOGM)

Inspector's Signature: Wayne Western #42 Date: 3/31/94

BOY0394.WHW