State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

GARY R. HERBERT
Governor
SPENCER J. COX
Lieutenant Governor

Division of Oil, Gas and Mining
JOHN R. BAZA
Division Director

Minerals Inspection Report

Reviewed PBT

Report Date: **04/21/2014**

Mine Name: Beaver Shaft and East Beaver Pile	Permit Number:	M/037/0026	Mine Status:	Active
Operator Name: Energy Fuels Resources (USA)	Inspection Date:	04/15/2014	Permit Fees:	Paid
Inspector(s): M. Bradley	Inspection Time:	09:15a	Bond Amount:	$348,686
Attendee(s): See below	Weather:	Clear, cool	Bond Escalation:	09/21/2015
Inspection Purpose: Routine inspection			Prior Inspection:	06/13/2013

Conclusions and Recommendations

UTM Location: Zone 12N; E652866m, N4242493m

Attendees: Becky Doolittle, BLM; Joe Manning, BLM; Andrea Reither, EFR; Stephen Downs, EFR; Race Fisher, EFR; Todd Eldredge, EFR.

No significant changes since last inspection. Some minor erosion on haul road on north side of East Beaver waste pile. Rancher continues to dump deceased livestock east of waste rock pile on BLM land. Beaver shaft area and buildings appeared secure. No visible environmental, public safety, or erosion problems noted.

	Elements of Inspection	Evaluated & Commented	Enforcement
1.	*Permits, Revisions, Transfer, Bonds*	☒	☐
	Fees current, bond escalation due in September 2015		
2.	*Public Safety (shafts, adits, trash, signs, highwalls)*	☒	☐
	No visible problems observed		
3.	*Protection of Drainages/Erosion Control*	☒	☐
	Minor erosion on haul road on north side of waste rock pile where rill had formed cutting through road block berm		
4.	*Deleterious Material*	☐	☐
5.	*Roads (maintenance, surfacing, dust control, safety)*	☐	☐
6.	*Reclamation*	☐	☐
7.	*Backfilling/Grading (trenches, pits, roads, highwalls, shafts)*	☐	☐
8.	*Soils*	☐	☐
9.	*Revegetation*	☒	☐
	Discussed areas where interim vegetation would be appropriate during temporary suspension		
10.	*Other*	☐	☐

Inspector's Signature: Michael R Bradley

CC: Becky Doolittle, BLM (rdoolitt@blm.gov)
Andrea Reither, EFR (areither@energyfuels.com)
Frank Filas, EFR (ffilas@energyfuels.com)
Mike George, UDWQ (mmgeorge@utah.gov)

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M037-SanJuan/M0370026-LaSalSnowballMines/Inspections/Beaver Shaft inspections/INSP-04152014B.pdf

Near hoist building looking west

Near hoist building looking southwest

Hoist building

Sealed shaft

Head frame

Ore hopper

East Beaver waste rock pile

East Beaver waste rock pile

Dead livestock dump east of waste rock pile

North slope of waste rock pile looking west

North slope of waste rock pile looking northeast

Minor erosion cutting through roadblock berm