Division of Oil, Gas, & Mining
Mining Report

07/22/93

MINE ID: M0450017 MINE NAME: MERCUR MINE

OPERATOR: BARRICK MERCUR GOLD MINES, INC
CONTACT: DAVID P. BEATTY
ADDRESS: P O BOX 838
TOOELE UT 84074

PHONE: (801)268-4447

Surface Owner: PRIVATE BLM #:
Mineral Owner: PRIVATE Lease #:

Qtr-Qtr-Qtr1	Qtr-Qtr1	Qtr1	Qtr-Qtr-Qtr2	Qtr-Qtr2	Qtr2	Sec	Town	Range
		PR				4	6.0S	3.0W
						8	6.0S	3.0W
						32	5.0S	3.0W

Permit Status: APP Mine Type [(S)urface, (U)nderground]: S

Mine Status (PRO,ACT,SUS,RET): ACT Acreage: 853

Minerals Mined
AU, AG

DATE RECEIVED	TENTATIVE APPROVAL DATE	FINAL APPROVAL DATE	LAST INSPECTED
03/10/81	05/01/81	10/13/81	07/13/93

BOND TYPE: SELF BOND BOND AMOUNT: $$8,808,891

ANNUAL REPORT YEAR: 92

	YTD	Total				
NONCOMP NOTICES:	0	0	DATE ISSUED:	/ /	DATE RESOLVED:	/ /
VIOLATIONS:	0	0	DATE ISSUED:	/ /	DATE RESOLVED:	/ /
REVISIONS:	0	0	DATE REC'D:	/ /	DATE APPROVED:	/ /
AMENDMENTS:	0	1	DATE REC'D:	03/11/92	DATE APPROVED:	05/18/92

COMMENTS:
INSPECTION MADE TO EVALAUTE AREAS RECENTLY RECLAIMED & TO PROPOSE RECLAMATION TECHNIQUES FOR DIFFICULT AREAS. BARRICK ATTEMPTED TO CAST TOPSOIL ONTO SNIDER DUMP, BUT WAS NOT SUCCESSFUL. DUMP TOO STEEP & SOIL SLID TO BOTTOM OF DUMP. TOP & UPPER PORTION OF THE SLOPES HAVE FORMES A DURABLE CRUST DUE TO THE CLAY CONTENT OF THE DUMP MATERIAL. CANNOT REGRADE THE DUMP TO A 2:1 BECAUSE IT MAY PLACE MATERIAL ON THE MAIN ACCESS ROAD BELOW. NORTH MERCUR DUMP IS AT ANGLE OF REPOSE & HOLDING HYDROMULCH MIX QUITE WELL. SNIDER DUMP NEEDS MORE INSPECTION.