

NOTES:

1. SEE PLATE 6-2 FOR OVERBURDEN AND MAXIMUM POTENTIAL SUBSIDENCE.
2. LONGWALL PANEL GEOMETRY MAY BE INFLUENCED BY GEOLOGIC ANOMALIES WHICH MAY INCLUDE, BUT ARE NOT LIMITED TO COAL THICKNESS, COAL QUALITY, AND MINING CONDITIONS. ADDITIONALLY, THE PROJECTED CLAY DIKE(S) MAY REDUCE RECOVERY IN LONGWALL PANEL 18.

I hereby certify that the design and/or map contained herein was prepared by me or under my supervision and is true and correct to the best of my knowledge.

OUTCROP

LEGEND

	LW	CM
2002 PRODUCTION AREA		
2003 PRODUCTION AREA		
2004 PRODUCTION AREA		
MINED AREAS		
PERMIT AREA		
EXISTING LEASE AREA		
SECTION LINES		
SURFACE DRILL HOLE	DH-4	
UNDERGROUND DRILL HOLE	DH-1	

RECEIVED
APR 0 7 2003
DIV. OF OIL, GAS & MINING

INCORPORATED
APR 0 2 2003
DIV OF OIL GAS & MINING

Note: Trimming and Projection May Change If South Crandall Lease Is Acquired.

Note: Access to open Federal Reserves (South Crandall LBA)

Plate 5-2

GENWAL RESOURCES, INC.

P.O. Box 1420 195 North 100 West Huntington, Utah 84528
Telephone (435) 687-9813

CRANDALL CANYON #1 MINE
MINING PROJECTIONS

DRAWN BY: JCL, GEG	MINE ID NO: 42-01715
DATE: 10-15-96	REV. DATE: 11-18-02
ACAD FILE: NEW0202	DRAWING NO.: PLATE 5-2

SCALE: 1"=600'