Area 3
Area 2
Area 1
Area 4
SD-6
SD-5
Area 9
Bryner Creek
SD-4
Area 8
Area 5
Area 6
Area 7
Right Fork

0 100' 200'

P:\Gordon Creek\Gordon Creek Channel Repair 2016.dwg

REGISTERED PROFESSIONAL ENGINEER
No. 8781250-2202
CRAIG WILLIAM BROWN
9/2/2016
STATE OF UTAH

INCORPORATED
SEP 28 2016
Div. of Oil, Gas & Mining

RECEIVED
SEP 07 2016
DIV. OF OIL, GAS & MINING

Plate 3-13
2015 Channel Repair Disturbance Areas
Gordon Creek 2/7/8 Mines

Canyon Fuel Company, LLC

HCR 35 BOX380, HELPER, UT, 84526 435-448-2632	DATE: 05/11/16	CK.BY: CHansen	REVISION: 1
CAD FILE:	SCALE: FULL	DR.BY: BBailey	9/2/2016
DWG. NO.: 000			