DEPARTMENT OF NATURAL RESOURCES - DIVISION OF OIL, GAS, AND MINING
1588 WEST NORTH TEMPLE - SALT LAKE CITY, UTAH 84116 - (801) 533-5771

56 64 16

STATE OF UTAH

0003

Notice of Violation No. N 80-1-11-1

Violation No. 1 of 1.

Nature of the Violation

FAILURE TO DIVERT OVERLAND FLOW AWAY FROM DISTURBED AREAS BY MEANS OF TEMPORARY OR PERMANENT DIVERSION STRUCTURES

Provision(s) of the Regulations, Act, or Permit Violated

MC 717.17(C)
TITLE 40-10-17(J)(ii)(A)

Portion of the Operation to which Notice Applies

SOWBELLY GULCH, PRICE RIVER COMPLEX #5 MINE ASSOCIATED AFFECTED AND UNAFFECTED AREAS.

Remedial Action Required (including interim steps, if any)

DIVERT OVERLAND FLOW AWAY FROM ALL DISTURBED AREAS
REMOVE ALL DEBRIS OR MATERIAL FROM TEMPORARY DIVERSION STRUCTURES SO AS NOT TO IMPAIR ALTER OR AFFECT THE INTENDED USE OF THE STRUCTURE. DIVERSIONS SHALL INCLUDE LININGS, VEGETATION OR OTHER APPLICABLE MEASURES TO MINIMIZE EROSION AND SEDIMENT LOADS.

Time for Abatement (including time for interim steps, if any)

30 DAYS NO LATER THAN 8:00 AM FRIDAY NOVEMBER 28TH, 1980

Ps

DEPARTMENT OF [illegible]URAL RESOURCES - DIVISION OF OIL [illegible]AS, AND MINING
1588 WEST NOR[illegible] TEMPLE - SALT LAKE CITY, UTAH 8411[illegible] (801) 533-5771

56 64 16

STATE OF UTAH

Notice of Violation No. N [illegible]

Violation No. 1 of 1.

Nature of the Violation

Provision(s) of the Regulations, Act, or Permit Violated

Portion of the Operation to which Notice Applies

Extension applies to: 1) extension of ditch on northeast side of materials pad so that the ditch continues north along its present course
2) put up berm on southern of parking lot near log rail and at end of fan access roads
3) straw bales in area where berm is breached just below culvert which takes undisturbed drainage into natural watercourse.

Remedial Action Required (including interim steps, if any)

Time for Abatement (including time for interim steps, if any)

30 day extension untill no later than 8:00 Am Tuesday January 27, 1981. [illegible] 12-16-80

INSPECTOR

1037