0033

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

Partial: ____ Complete: XX Exploration ____
Inspection Date/Time: November 15, 1993/08:30am-02:00pm
Date of Last Inspection: October 27, 1993

Mine Name: Skyline Mine County: Carbon Permit Number: ACT/007/005
Permittee and/or Operator's Name: Coastal States Energy/Utah Fuel
Business Address: P. O. Box 719, Helper, UT 84527
Type of Mining Activity: Underground XX Surface ____ Prep. Plant ____ Other ____
Officials(s): State: Stephen J. Demczak Company: Keith Zobell
Federal Official(s): _____ Weather Conditions: Cold 6" Snow
Existing Acres: Permitted-7067.11 Disturbed-62.08 Regraded-Seeded- Bonded-62.41
Increased/Decreased: Permitted-____ Disturbed-__ Regraded-__ Seeded-__ Bonded-____
Status: ___Exploration/ X Active/ ___Inactive/ __Temp Cessation/ __Bond Forfeiture
Reclamation (__Phase I/ __Phase II/ __Final Bond Release/ __Liability _____ Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
   a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
   b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[XX]	[ ]	[XX]	[ ]
2.	SIGNS AND MARKERS	[XX]	[ ]	[ ]	[ ]
3.	TOPSOIL	[XX]	[ ]	[ ]	[ ]
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[XX]	[ ]	[XX]	[ ]
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[XX]	[ ]	[ ]	[ ]
c.	OTHER SEDIMENT CONTROL MEASURES	[XX]	[ ]	[ ]	[ ]
d.	WATER MONITORING	[XX]	[ ]	[ ]	[ ]
e.	EFFLUENT LIMITATIONS	[XX]	[ ]	[ ]	[ ]
5.	EXPLOSIVES	[XX]	[ ]	[ ]	[ ]
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[XX]	[ ]	[ ]	[ ]
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[XX]	[ ]	[ ]	[ ]
8.	NONCOAL WASTE	[XX]	[ ]	[XX]	[ ]
9.	PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[XX]	[ ]	[ ]	[ ]
10.	SLIDES AND OTHER DAMAGE	[XX]	[ ]	[ ]	[ ]
11.	CONTEMPORANEOUS RECLAMATION	[XX]	[ ]	[ ]	[ ]
12.	BACKFILLING AND GRADING	[XX]	[ ]	[ ]	[ ]
13.	REVEGETATION	[XX]	[ ]	[ ]	[ ]
14.	SUBSIDENCE CONTROL	[XX]	[ ]	[ ]	[ ]
15.	CESSATION OF OPERATIONS	[XX]	[ ]	[ ]	[ ]
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[XX]	[ ]	[ ]	[ ]
b.	DRAINAGE CONTROLS	[XX]	[ ]	[ ]	[ ]
17.	OTHER TRANSPORTATION FACILITIES	[XX]	[ ]	[XX]	[ ]
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[XX]	[ ]	[ ]	[ ]
19.	AVS CHECK (4th Quarter-April, May, June) _____ date	[XX]	[ ]	[ ]	[ ]
20.	AIR QUALITY PERMIT	[XX]	[ ]	[ ]	[ ]
21.	BONDING & INSURANCE	[XX]	[ ]	[ ]	[ ]

PERMIT NUMBER: ACT/007/005 DATE OF INSPECTION: November 15, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permit -

a) Insurance has been renewed by Flat Top and expires 12-31-93. The accord is in compliance with regulation.

b) The reclamation agreement was signed by the permittee and the Division Director. The new agreement has set the bond amount to $3,180,000.

c) Subsidence--The aerial survey for subsidence was flown September 28, 1993. A subsidence report is being compiled by the survey and will be submitted to the Division and will be included in the annual report.

d) Sediment ponds were inspected on October 25, 1993. There were no performance standards violated or structural damage noticed by the inspection.

e) The refuse pile was inspected and the formal certified report was written and sent to the Division on November 8, 1993. The refuse pile showed no signs of hazard conditions.

f) The water monitoring data was examined and CS-2 was checked for water parameter. All required parameters were taken. No problems were noticed.

g) Reviewed information and designs of the ASCA's areas to be submitted to Division concerning NOV 93-39-5-3, violation 1 of 3. The submittal should abate the NOV once the Division has reviewed the material.

h) The plans for the mine and refuse pond to abate the NOV 93-39-5-3, violation 2 of 3 was submitted to the Division. An extension is requested for review time.