0022

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

INSPECTION REPORT

Partial: XXX Complete:__ Exploration:__
Inspection Date & Time: 4/23/96 / 8:00a.m.-2:00p.m.
Date of Last Inspection: 3/20/96

Mine Name: Skyline Mine County: Carbon Permit Number: **ACT/007/005**
Permittee and/or Operator's Name: Utah Fuel Company
Business Address: P.O.Box 719, Helper, Utah 84526
Type of Mining Activity: UndergroundXXX Surface__ Prep. Plant__ Other__
Company Official(s): Keith Zobell
State Officials(s): Stephen J. Demczak Federal Official(s):
Weather Conditions: Warm, 40's
Existing Acreage: Permitted-7067.11 Disturbed- 62.08 Regraded-__ Seeded-__ Bonded-65.38
Increased/Decreased: Permitted-___ Disturbed-___ Regraded-___ Seeded-___ Bonded-___
Status: ___Exploration/XXX Active/__Inactive/__Temporary Cessation/___Bond Forfeiture
Reclamation (___Phase I/__Phase II/__Final Bond Release/__Liability_____Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions
1. Substantiate the elements on this inspection by checking the appropriate performance standard.
   a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
   b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[ ]	[ ]	[ ]	[ ]
2. SIGNS AND MARKERS	[ ]	[ ]	[ ]	[ ]
3. TOPSOIL	[XX]	[ ]	[XX]	[ ]
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	[XX]	[ ]	[XX]	[ ]
b. SEDIMENT PONDS AND IMPOUNDMENTS	[XX]	[ ]	[XX]	[ ]
c. OTHER SEDIMENT CONTROL MEASURES	[XX]	[ ]	[XX]	[ ]
d. WATER MONITORING	[ ]	[ ]	[ ]	[ ]
e. EFFLUENT LIMITATIONS	[ ]	[ ]	[ ]	[ ]
5. EXPLOSIVES	[ ]	[ ]	[ ]	[ ]
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[ ]	[ ]	[ ]	[ ]
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[ ]	[ ]	[ ]	[ ]
8. NONCOAL WASTE	[ ]	[ ]	[ ]	[ ]
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[ ]	[ ]	[ ]	[ ]
10. SLIDES AND OTHER DAMAGE	[ ]	[ ]	[ ]	[ ]
11. CONTEMPORANEOUS RECLAMATION	[ ]	[ ]	[ ]	[ ]
12. BACKFILLING AND GRADING	[ ]	[ ]	[ ]	[ ]
13. REVEGETATION	[ ]	[ ]	[ ]	[ ]
14. SUBSIDENCE CONTROL	[ ]	[ ]	[ ]	[ ]
15. CESSATION OF OPERATIONS	[ ]	[ ]	[ ]	[ ]
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	[ ]	[ ]	[ ]	[ ]
b. DRAINAGE CONTROLS	[ ]	[ ]	[ ]	[ ]
17. OTHER TRANSPORTATION FACILITIES	[ ]	[ ]	[ ]	[ ]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[ ]	[ ]	[ ]	[ ]
19. AVS CHECK (4th Quarter-April, May, June)_____(date)	[ ]	[ ]	[ ]	[ ]
20. AIR QUALITY PERMIT	[ ]	[ ]	[ ]	[ ]
21. BONDING & INSURANCE	[ ]	[ ]	[ ]	[ ]

INSPECTION REPORT
(Continuation sheet)

PERMIT NUMBER: **ACT/007/005** DATE OF INSPECTION: 4/23/96

(Comments are Numbered to Correspond with Topics Listed Above)

3. TOPSOIL -

The topsoil stockpiles at Skyline are still under snow; therefore, it is impossible to evaluate.

4A. DIVERSIONS -

The diversion ditches were recently cleaned out and were functioning as designed. Water was being conveyed by these ditches and was going into the sediment ponds as required in the Mining and Reclamation Plan.

4B. SEDIMENT PONDS -

The sediment ponds were inspected with no hazardous conditions being noticed. The mine site pond was the only pond discharging during the inspection. It is planned that this pond will be cleaned out in 1996.

4C. OTHER SEDIMENT CONTROL MEASURES -

The majority of the alternate sediment control measures are still under snow and therefore inspection of these installations is impossible.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Keith Zobell (Utah Fuel) Marcia Petta (OSM)
Given to: Joe Helfrich (DOGM) Filed to: Price Field Office
Date: May 1, 1996

Inspector's Signature: #39
Stephen J. Demczak