0032

State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

1594 West North Temple, Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

June 4, 1997

Mr. Dan Meadors, General Manager
Canyon Fuel Company, LLC
P. O. Box 719
Helper, Utah 84526

Re: Inadequate Mine Plan Maps, Canyon Fuel Company, LLC, Skyline Mine, ACT/007/005, Folder #3, Carbon County, Utah

Dear Mr. Meadors:

During our recent evaluation of your annual report, we identified a problem that needs to be corrected. The maps that show mining projections in the annual reports are substantially different than those maps in your approved mining and reclamation plan (MRP). Some deviation in these maps would be expected, but upon further investigation, we found that the maps in your MRP are out of date and are inadequate. In order for Canyon Fuel to achieve compliance, revised mine maps must be submitted which show the boundaries of all areas to be affected, a description of size, and timing and sequence of mining for the term of the permit as required by R645-301-521.140 and R645-301-525.270.

The required maps (certified) will need to be submitted through the permit change process, with the appropriate forms. Seven copies are needed for review and distribution. Thank you for your attention to this matter. If you have any questions, please don't hesitate to call me at 538-5306 or Daron Haddock, Permit Supervisor at 538-5325.

Sincerely,

Mary Ann Wright
Associate Director of Mining

tt
cc: Barry Barnum
O:\007005.SKY\FINAL\MINEMAPS.LET